

UNCLASSIFIED

AD NUMBER

AD880290

LIMITATION CHANGES

TO:

Approved for public release; distribution is unlimited.

FROM:

Distribution authorized to U.S. Gov't. agencies and their contractors; Critical Technology; NOV 1970. Other requests shall be referred to U.S. Army Aviation Materiel Laboratories, Fort Eustis, VA 23604. This document contains export-controlled technical data.

AUTHORITY

USAAMRDL ltr, 23 Jun 1971

THIS PAGE IS UNCLASSIFIED

AD No. _____
DDC FILE COPY

AD880290

AD

USAALABS TECHNICAL REPORT 70-49B
FATIGUE STRENGTH OF LUGS
CONTAINING LINERS
VOLUME II
COMPUTER PROGRAM USED FOR ANALYSES

GD
CB

By

Robert J. Mayerjak


November 1970

U. S. ARMY AVIATION MATERIEL LABORATORIES
FORT EUSTIS, VIRGINIA

CONTRACT DAAJ02-67-C-0066 ✓

KAMAN AEROSPACE CORPORATION
BLOOMFIELD, CONNECTICUT

This document is subject to special
export controls, and each transmittal
to foreign governments or foreign
nationals may be made only with
prior approval of U.S. Army Aviation
Materiel Laboratories, Fort Eustis,
Virginia 23604.



DISCLAIMERS

The findings in this report are not to be construed as an official Department of the Army position unless so designated by other authorized documents.

When Government drawings, specifications, or other data are used for any purpose other than in connection with a definitely related Government procurement operation, the United States Government thereby incurs no responsibility nor any obligation whatsoever; and the fact that the Government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data is not to be regarded by implication or otherwise as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission, to manufacture, use, or sell any patented invention that may in any way be related thereto.

DISPOSITION INSTRUCTIONS

Destroy this report when no longer needed. Do not return it to the originator.

RECORDED FOR	
GSFSI	WHITE SECTION <input type="checkbox"/>
DOC	BUFF SECTION <input type="checkbox"/>
MAILED	<input type="checkbox"/>
INDICATION
.....	
BY	
DISTRIBUTION/AVAILABILITY CODES	
DIST.	AVAIL. AND OR SPECIAL
24	



DEPARTMENT OF THE ARMY
HEADQUARTERS US ARMY AVIATION MATERIEL LABORATORIES
FORT EUSTIS, VIRGINIA 23604

The pin-loaded lug is a structural element of considerable importance in aircraft design, particularly in the design of helicopter rotor and control systems. Much work has been done in the analysis of lugs subjected to static loads. As a result, the static analysis of lugs has been reduced to a well-established rational convention, the most notable work being a much-referenced paper by Melcon and Hoblit wherein design allowables and an interaction formula for statically loaded aluminum and steel alloy lugs are reported. In contrast to the static case, no analogous design criterion exists for the design of lugs simultaneously subjected to axial and transverse fatigue loads. A most glaring testimony to the dearth of valid experimental data on pin-loaded lugs is demonstrated in MIL-HDBK-5A, wherein the section on joints offers no design guidance for lugs.

This contract was initiated to:

- Evaluate the fatigue strength of lugs subjected to vibratory loadings at various orientations to the lug axis of symmetry. More specifically, an interaction formula relating load orientation to lug endurance limit was sought.
- Substantiate the photoelastically established benefits in lug fatigue strength that can be derived through selection of interference fit.
- Determine the influence of edge distance and material on lug fatigue strength.

Seventy-three lug specimens were validly failed by step-testing leading to the development of design charts in the form of modified Goodman diagrams for each material, load direction, and interference fit at two probability-of-failure levels. These charts compare favorably with test results reported in the literature and satisfy structural requirements for a range of edge-distance and load ratios particularly suitable for use in helicopter design. Development of an interaction formula did not materialize. Excessive scatter in the data precluded development of a general interaction formula applicable to both steel and titanium for each edge-distance ratio tested. A specific interaction formula for each configuration tested, although possible, was not pursued.

Results conclusively demonstrate that lug fatigue strength is materially improved by the introduction of high interference fit. Verification of the existence of an optimum interference fit as photoelastically predicted was inconclusive. For the high-modulus materials tested, the level of interference obtainable was limited by attainable thermal size changes. Thus, the "optimum" was the maximum attainable interference fit not causing lug yield. For lugs of lower modulus, such as aluminum or steel and titanium lugs with liners having substantially heavier wall thickness, it is believed that an optimum interference fit does exist beyond which increased interference would be detrimental.

Task 1F162204A14601
Contract DAAJ02-67-C-0066
USAAVLABS Technical Report 70-49B
November 1970

**FATIGUE STRENGTH OF LUGS
CONTAINING LINERS**

**VOLUME II
COMPUTER PROGRAM
USED FOR ANALYSES**

By
Robert Mayerjak

Prepared by
**Kaman Aerospace Corporation
Bloomfield, Connecticut**

For
**U. S. ARMY AVIATION MATERIEL LABORATORIES
FORT EUSTIS, VIRGINIA**

This document is subject to special export controls, and each transmittal to foreign governments or foreign nationals, may be made only with prior approval of U. S. Army Aviation Materiel Laboratories, Fort Eustis, Virginia 23604.

SUMMARY

This report presents a FORTRAN program for the analysis of elastic, two-dimensional, plane-stress structures. Examples show the application of the program to the analysis of lugs.

FOREWORD

This project was performed under Contract DAAJ02-67-C-0066, Task 1F162204A14601, under the cognizance of Mr. Joseph H. McGarvey of the Aeromechanics Division of USAAVLABS.

The tests and analyses were conducted at the Kaman Aerospace Corporation.

The report consists of two volumes:

Volume I, Results

Volume II, Computer Program Used for Analyses

The computer program presented herein was developed with contractor funds prior to the contract. The very significant contributions of Mr. Alex Berman and Dr. John Hsu to the computer program are gratefully acknowledged.

TABLE OF CONTENTS

	<u>Page</u>
SUMMARY	iii
FOREWORD	v
LIST OF ILLUSTRATIONS	viii
LIST OF SYMBOLS	ix
INTRODUCTION	1
STIFFNESS MATRICES FOR QUADRILATERAL ELEMENT	3
INSTRUCTIONS FOR USER	6
GENERAL	6
INPUT DESCRIPTION	10
BLOCK OUTLINE FOR INPUT DATA	11
OUTPUT DESCRIPTION	12
EXAMPLE 1	13
EXAMPLE 2	15
EXAMPLE 3	25
SOURCE PROGRAM	53
PROCESSING INFORMATION	53
FLOW DIAGRAM FOR MA2B	53
SOURCE PROGRAM DESCRIPTION	54
FORTRAN LISTING	56
DISTRIBUTION	78

LIST OF ILLUSTRATIONS

<u>Figure</u>		<u>Page</u>
1	Coordinates for Quadrilateral Element	3
2	Local Coordinates	8
3	Node Identifications P-Q-R-S for Quadrilateral Element	9
4	Structure for Example 1	14
5	Structure and Results for Example 2	23
6	Structure for Example 3	45
7	Tangential Stress Versus Radial Position for Example 3	51
8	Tangential Stress Versus Angular Position for Example 3	52

LIST OF SYMBOLS

A	matrix of compatible strain distribution due to element displacements
A_1, A_2, A_3	components of matrix A
B C	matrices of coefficients occurring in the generalized Hooke's Law Equation, $\sigma = C e - B \alpha T$
	$B = \frac{E}{1-\nu} \begin{Bmatrix} 1 \\ 1 \\ 0 \end{Bmatrix} \quad C = \frac{E}{(1-\nu^2)} \begin{bmatrix} 1-\nu & \nu & 0 \\ \nu & 1 & 0 \\ 0 & 0 & \frac{1-\nu}{2} \end{bmatrix}$
D	column matrix of constants for assumed strain function
e	column matrix of total strains
E	Young's modulus
F	matrix of coordinate terms
h	thermal stiffness matrix
K	element stiffness matrix
T	element temperature
u	column matrix of element displacements
u_x, u_y	displacements in the x and y directions, respectively
V	volume
x, y	local Cartesian coordinates
X Y	datum Cartesian coordinates
α	coefficient of thermal expansion
ν	Poisson's ratio
σ	column matrix of element stresses

INTRODUCTION

This volume presents a FORTRAN program which was used to calculate the stresses in the lugs reported in Volume I. The program is named MA2B, which is an abbreviation for matrix analysis, two-dimensional structures, program version B. The information reported herein will enable the reader to use the program and to modify it, if desired.

MA2B is itself a modification of another program*. This reference provides excellent, lucid derivations and descriptions of the structural analysis methods and the basic logic used in programming. It is believed that it contained the first well-documented, general-purpose structural analysis program made available without proprietary restrictions. This volume draws heavily from the referenced document.

Program MA2B differs from its parent in four ways:

1. It contains a general, quadrilateral-shaped element.
2. It uses a special Gauss-elimination algorithm for the solution of the simultaneous equations.
3. It is restricted to two-dimensional analysis.
4. It uses more compact input and output.

The incorporation of a general, quadrilateral-shaped element is particularly important for problems with curved boundaries, such as lugs. For these problems the quadrilateral element gives more accurate and more easily interpreted results. The special Gauss-elimination algorithm greatly increased the number of nodes which could be used for a given core memory size. The algorithm stores only the non-zero elements of the upper triangle of the master stiffness matrix plus up to five columns of non-zero forces. Two facts are noteworthy regarding this technique:

* Przemieniecki, J.S., and Berke, Laszlo, DIGITAL COMPUTER PROGRAM FOR THE ANALYSIS OF AEROSPACE STRUCTURES BY THE MATRIX DISPLACEMENT METHOD, FDL TDR 64-18, AF Flight Dynamics Laboratory, Wright-Patterson Air Force Base, Ohio, April 1964, AD600418.

1. The economy of storage exists even if a few elements in the stiffness matrix are very widely spaced (not banded about the diagonal).
2. The number of nodes that can be used increases in linear proportion to the size of the available core.

MA2B was restricted to two-dimensional analysis to increase further the number of nodes that could be used. As a result of the changes, MA2B can solve problems with 300 node points using double precision arithmetic. For comparison, the referenced program allowed only 70 nodes and used single precision arithmetic. As a consequence of the increased size of the problem that could be handled, it became desirable to change the input and output to more compact block tabular forms.

STIFFNESS MATRICES FOR QUADRILATERAL ELEMENT

The referenced document provides a complete presentation of the method used, including derivations of all equations. This section describes only the additions that were made.

The coordinate system used for the quadrilateral element is shown in Figure 1.




Figure 1. Coordinates for Quadrilateral Element.

The stiffness matrix for the quadrilateral element was calculated using the assumed displacement function:

$$u_x = D_1 + D_2 \alpha + D_3 \gamma + D_4 \alpha \gamma$$

$$u_y = D_5 + D_6 \alpha + D_7 \gamma + D_8 \alpha \gamma$$

If P-Q is not perpendicular to R-S, the constants can be determined from the given coordinates for points P-Q-R-S, called 1-2-3-4, respectively. Thus,

$$\begin{bmatrix} u_1 \\ u_2 \\ u_3 \\ u_4 \\ u_5 \\ u_6 \\ u_7 \\ u_8 \end{bmatrix} = \begin{bmatrix} 1 & \alpha_1 & \gamma_1 & \alpha_1 \gamma_1 & 0 & 0 & 0 & 0 \\ 0 & 0 & 0 & 0 & 1 & \alpha_1 & \gamma_1 & \alpha_1 \gamma_1 \\ 1 & \alpha_2 & \gamma_2 & \alpha_2 \gamma_2 & 0 & 0 & 0 & 0 \\ 0 & 0 & 0 & 0 & 1 & \alpha_2 & \gamma_2 & \alpha_2 \gamma_2 \\ 1 & \alpha_3 & \gamma_3 & \alpha_3 \gamma_3 & 0 & 0 & 0 & 0 \\ 0 & 0 & 0 & 0 & 1 & \alpha_3 & \gamma_3 & \alpha_3 \gamma_3 \\ 1 & \alpha_4 & \gamma_4 & \alpha_4 \gamma_4 & 0 & 0 & 0 & 0 \\ 0 & 0 & 0 & 0 & 1 & \alpha_4 & \gamma_4 & \alpha_4 \gamma_4 \end{bmatrix} \begin{bmatrix} D_1 \\ D_2 \\ D_3 \\ D_4 \\ D_5 \\ D_6 \\ D_7 \\ D_8 \end{bmatrix}$$

$$u = F^{-1} D$$

$$D = F u$$

It can be shown that all elements of F are zero except

$$F_{11} = F_{52} = 1.0$$

$$F_{21} = F_{62} = (\gamma_3 \gamma_3 - \gamma_4 \gamma_4 + \gamma_4 \gamma_3 (\gamma_4 - \gamma_3) / \gamma_2) / p$$

$$F_{23} = F_{63} = \gamma_3 \gamma_4 (\gamma_3 - \gamma_4) / (p \gamma_2)$$

$$F_{25} = F_{66} = \gamma_4 \gamma_4 / p$$

$$F_{27} = F_{68} = -\gamma_3 \gamma_3 / p$$

$$F_{31} = -F_{33} = F_{72} = -F_{74} = -1.0 / \gamma_2$$

$$F_{41} = F_{82} = ((\gamma_4 - \gamma_3) + (\gamma_3 \gamma_4 - \gamma_4 \gamma_3) / \gamma_2) / p$$

$$F_{43} = F_{84} = (\gamma_4 \gamma_3 - \gamma_3 \gamma_4) / (p \gamma_2)$$

$$F_{45} = F_{86} = -\gamma_4 / p$$

$$F_{47} = F_{88} = \gamma_3 / p$$

where $p = \gamma_3 \gamma_4 (\gamma_4 - \gamma_3)$ and the hierarchy of operations of FORTRAN apply.

The strains become

$$\mathbf{e} = \begin{bmatrix} e_{xx} \\ e_{yy} \\ e_{xy} \end{bmatrix} = \begin{bmatrix} \frac{\partial u_x}{\partial x} \\ \frac{\partial u_y}{\partial y} \\ \frac{\partial u_x}{\partial y} + \frac{\partial u_y}{\partial x} \end{bmatrix} = \begin{bmatrix} D_2 + D_4 \gamma \\ D_7 + D_8 \gamma \\ D_3 + D_4 \gamma + D_6 + D_8 \gamma \end{bmatrix}$$

$$\mathbf{e} = \mathbf{A} \mathbf{u}$$

$$\mathbf{A} = \begin{bmatrix} (F_{21} + F_{41} \gamma) (F_{22} + F_{42} \gamma) & \dots & (F_{28} + F_{48} \gamma) \\ (F_{71} + F_{81} \gamma) (F_{72} + F_{82} \gamma) & \dots & (F_{78} + F_{88} \gamma) \\ (F_{31} + F_{61} + F_{41} \gamma + F_{81} \gamma) \dots (F_{38} + F_{68} + F_{48} \gamma + F_{88} \gamma) \end{bmatrix}$$

The element stiffness matrices k and h were calculated using the unit displacement theorem.

$$k = \int_V A^T C A \, dV$$

$$h = \int_V A^T B \, dV$$

The matrix A was considered to be composed of 3 components.

$$A = A_1 + A_2 x + A_3 y$$

$$A_1 = \begin{bmatrix} F_{21} & \dots & F_{28} \\ F_{71} & \dots & F_{78} \\ (F_{31} + F_{61}) & \dots & (F_{38} + F_{68}) \end{bmatrix}, \quad A_2 = \begin{bmatrix} 0 & \dots & 0 \\ F_{81} & \dots & F_{88} \\ F_{41} & \dots & F_{48} \end{bmatrix}, \quad A_3 = \begin{bmatrix} F_{41} & \dots & F_{48} \\ 0 & \dots & 0 \\ F_{81} & \dots & F_{88} \end{bmatrix}$$

Then,

$$\begin{aligned} k = & \int_V A_1^T C A_1 \, dV + (A_1^T C A_2 + A_2^T C A_1) \int_V x \, dV \\ & + (A_1^T C A_3 + A_3^T C A_1) \int_V y \, dV \\ & + (A_2^T C A_3 + A_3^T C A_2) \int_V xy \, dV \\ & + A_2^T C A_3 \int_V x^2 \, dV + A_3^T C A_2 \int_V y^2 \, dV \end{aligned}$$

$$h = - \int_V A_1^T B \, dV - A_2^T B \int_V x \, dV - A_3^T B \int_V y \, dV$$

INSTRUCTIONS FOR USER

This section provides instructions for using the program and describes in detail the input and output. Complete examples are given to demonstrate the use of the program.

GENERAL

The following comments provide general guidance for input preparation.

Units

Any consistent set of units may be used for the input. The output will have corresponding units. The following units are recommended:

input: Loads, kips	output: forces, kips
lengths, in.	deflections, in.
E, ksi	stresses, ksi

Shape of Elements

The program will run to completion with almost any combination of elements. The only element which kills the program is a special quadrilateral element described in more detail later in these comments. In most cases, the results will have engineering significance even for very oddly shaped elements. However, the best results for stress analysis will be obtained if the following rules are applied:

1. Avoid panel elements with large length-to-width ratios.
2. Avoid mixing triangular and quadrilateral elements in the region of interest. The triangular elements will appear to be stiffer and will disturb the stress distribution.
3. Use a gradual transition from large-to small-sized elements.
4. Use quadrilateral elements which are nearly rectangles.
5. Orient the local axes of the quadrilateral elements in the direction of anticipated principal stresses.

Number of Nodes

The permissible number of nodes is limited by the number of non-zero elements that are developed in the stiffness matrix and the loading conditions, both initially and during the course of the Gaussian elimination. The program is dimensioned to handle 6000 non-zero elements. How many nodes this corresponds to is indeterminate. However, for a typical structure, 300 node points can be used if the nodes are numbered judiciously. For example, the lug described herein had 258 node points and developed less than 4200 non-zero elements. The objective in node-point numbering is to avoid interspersing high and low node-point numbers. A good practice is to assign the node numbers consecutively, starting at one end of the structure and proceeding systematically to the other end. This will cause the stiffness matrix to become a desirable narrow band along the diagonal and will make the results more easily interpreted. If the structure is closed, the above-described procedure will cause the highest node numbers to become adjacent to the lowest numbers. This is not to be feared. It will not appreciably disturb the Gaussian elimination procedure used herein.

Number of Elements

Any number of elements can be used.

Number of Loading Cases

Up to five loading cases can be analyzed simultaneously, with a small increase in computation time. However, it is important to note that a large number of non-zero terms can be created if several loading conditions are used which have many node points loaded mechanically or by thermal forces. For such cases, the permissible number of nodes is less than if the load cases were done one at a time.

Datum Coordinates

Any convenient origin for datum coordinates may be used. Either right-hand or left-hand systems may be used.

Support Conditions

The support conditions are specified by placing the letter S after the coordinate, in a proper column. The computer will then prohibit the displacement of that node point in the

direction of the coordinate. Sufficient supports must be defined to enable the structure to be stable for any loading condition.

Mechanical Loads

The actual mechanical loads acting upon the real structure must be applied as concentrated forces acting at the node points of the idealized structure. The directions of the forces must correspond to datum coordinates, not local coordinates.

Thermal Loads

Thermal stresses can be determined by specifying a coefficient of thermal expansion and a temperature for each element. The temperature distribution in the real structure must be represented by temperatures which can vary from element to element, but which are constant within each element. If no thermal loads are applied, simply leave the input spaces blank.

Element Identification

The element identification number IE may be assigned randomly. However, a systematic assignment will be very helpful for finding the element during the interpretation of the output.

Local Coordinates

The node numbers of the vertices of each element are used to define both the position of the element and a set of local coordinates. The node numbers appear in the input as IP, IQ, IR, and IS; they correspond to the points P-Q-R-S shown in Figure 2.




Figure 2. Local Coordinates.

The local coordinates xy shown in Figure 2 conform to the following rules: For bar elements, local x has the direction and sense of a line drawn from P to Q . For panel elements, y has the direction and sense of a line drawn from P to Q . Local x is perpendicular to y . Local x has a sense that can be established using the right-hand rule, considering local z to be coming out of the sheet.

The direction of local coordinates is important because the stresses will be calculated and presented in the output using the local coordinate system.

A Special Requirement for a Quadrilateral

$P-Q-R-S$ for a quadrilateral must be selected in consecutive order around the element. Best results will be obtained if $R-S$ is relatively parallel to $P-Q$. If the $R-S$ direction were chosen to be perpendicular to the $P-Q$ direction, as shown in Figure 3, the method of analysis would break down. Under such conditions, the coefficients D for the assumed displacement function could not be determined uniquely from the coordinates of the vertices of the quadrilateral element. The matrix F would be singular. The condition can always be avoided by a simple change of designation for $P-Q-R-S$, as shown in Figure 3.




Figure 3. Node Identifications $P-Q-R-S$ for Quadrilateral Element.

INPUT DESCRIPTION

Name	Description	Name	Description
RH	heading	IE	identification number for element
NPDES	number of nodes	IP, IQ, IR, IS	node numbers for corners of the element, corresponding to P, Q, R, S
NELEM	number of elements	NT	number identifying element type, use: NT = 1 for bar element NT = 2 for triangular panel element NT = 3 for quadrilateral panel element
NC	number of load cases, no more than 5	TH	thickness of panel element or area of bar element
NC	number of loaded nodes	E	Young's modulus of elasticity
NIN	node number for first coordinate on card.	ALPHA	coefficient of thermal expansion
M	See Note 1.	PR	Poisson's ratio
N	node number for last coordinate on card. Note: N \leq M + 6	PR	temperature of element for loading case J
C	Identification symbol for coordinate direction, use: C = X for X-direction C = Y for Y-direction	ICONT	control symbol for next job. Use: ICONT = 1 if analysis of a new structure is desired. Begin input for new structure at RH, heading card.
X(J)	X-coordinate for node J, datum		ICONT = 2 to end calculations
Y(J)	Y-coordinate for node J, datum		
S	support condition for node J in direction of coordinate. Leave blank if node is free of external support. Use S = 6 if support exists.		
K	node number for load application point. See Notes 2.	NOTES :	
L	identification symbol for load direction, use: L = X for loads in X-direction L = Y for loads in Y-direction		1. The input of coordinates is done in two groups. All X-coordinates must go in first; then, all Y-coordinates. Up to seven coordinates can be used per card. The number M and N identify the node numbers for the coordinates on each card.
QX(J)	X-direction load at node K for case J		2. The input of mechanical loading is done for each loading point in turn. Two cards are required for each point. The first must contain the X-direction loads. The second the Y-direction loads. If there are no mechanical loads but only thermally induced loads, omit items K, L, QX(J) and QY(J).
QY(J)	Y-direction load at node K for case J		

BLOCK OUTLINE FOR INPUT DATA

-COLUMN NUMBER CA DATA CARD FCR ENC CF FILE

RH	NNODES	NELEM	(W)HICLE	CARD	WAY	EE USEC
0	0	0	0	0	0	0

CONTINUE UNTIL X-CORDINATE INPUT IS COMPLETE

M	N	C	$y(m)$	S	$y(m+1)$	S	$y(m+2)$	S	$y(m+3)$	S	$y(m+4)$	S	$y(m+5)$	S	$y(m+6)$	S	$y(m+7)$	S	$y(m+8)$	S	$y(m+9)$	S	$y(m+10)$	S	$y(m+11)$	S	$y(m+12)$	S	$y(m+13)$	S	$y(m+14)$	S	$y(m+15)$	S	$y(m+16)$	S	$y(m+17)$	S	$y(m+18)$	S	$y(m+19)$	S	$y(m+20)$	S	$y(m+21)$	S	$y(m+22)$	S	$y(m+23)$	S	$y(m+24)$	S	$y(m+25)$	S	$y(m+26)$	S	$y(m+27)$	S	$y(m+28)$	S	$y(m+29)$	S	$y(m+30)$	S	$y(m+31)$	S	$y(m+32)$	S	$y(m+33)$	S	$y(m+34)$	S	$y(m+35)$	S	$y(m+36)$	S	$y(m+37)$	S	$y(m+38)$	S	$y(m+39)$	S	$y(m+40)$	S	$y(m+41)$	S	$y(m+42)$	S	$y(m+43)$	S	$y(m+44)$	S	$y(m+45)$	S	$y(m+46)$	S	$y(m+47)$	S	$y(m+48)$	S	$y(m+49)$	S	$y(m+50)$	S	$y(m+51)$	S	$y(m+52)$	S	$y(m+53)$	S	$y(m+54)$	S	$y(m+55)$	S	$y(m+56)$	S	$y(m+57)$	S	$y(m+58)$	S	$y(m+59)$	S	$y(m+60)$	S	$y(m+61)$	S	$y(m+62)$	S	$y(m+63)$	S	$y(m+64)$	S	$y(m+65)$	S	$y(m+66)$	S	$y(m+67)$	S	$y(m+68)$	S	$y(m+69)$	S	$y(m+70)$	S	$y(m+71)$	S	$y(m+72)$	S	$y(m+73)$	S	$y(m+74)$	S	$y(m+75)$	S	$y(m+76)$	S	$y(m+77)$	S	$y(m+78)$	S	$y(m+79)$	S	$y(m+80)$	S	$y(m+81)$	S	$y(m+82)$	S	$y(m+83)$	S	$y(m+84)$	S	$y(m+85)$	S	$y(m+86)$	S	$y(m+87)$	S	$y(m+88)$	S	$y(m+89)$	S	$y(m+90)$	S	$y(m+91)$	S	$y(m+92)$	S	$y(m+93)$	S	$y(m+94)$	S	$y(m+95)$	S	$y(m+96)$	S	$y(m+97)$	S	$y(m+98)$	S	$y(m+99)$	S	$y(m+100)$	S
---	---	---	--------	---	----------	---	----------	---	----------	---	----------	---	----------	---	----------	---	----------	---	----------	---	----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	-----------	---	------------	---

CONTINUE UNTIL Y-COORDINATE INPUT IS COMPLETE

10	1	1	1
20	QX(1)	QY(1)	QY(1)
30	QX(2)	QY(2)	QY(2)
40	QX(3)	QX(4)	QX(4)
50			
60			

CONTINUE UNTIL MECHANICAL LOCATING INFILTRATION IS COMPLETE

1E	IP	ID	IR	IS	NT	IS	NT	IR	ID	IP	1E
30	40	50	55	60	65	70	75	80	85	90	95
T(1)	T(2)	T(3)	T(4)	T(5)							
PR	E	ALP <i>+</i> A									
1E	IP	ID	IR	IS	NT	IS	NT	IR	ID	IP	1E

CONTINUE, ONE CARD FOR EACH ELEMENT

NOTE. IF TH IS LEFT BLANK, THE COMPUTER WILL TAKE THE QUANTITIES TH, F, ALPHA, PR, AND T(J) EQUAL TO THE LAST VALUES ESTABLISHED FOR THESE QUANTITIES. THE USER SHOULD TAKE ADVANTAGE OF THIS FEATURE TO SAVE KEYPUNCHING.

OUTPUT DESCRIPTION

<u>Name</u>	<u>Description</u>
XX	normal stress parallel to the local x-coordinate
YY	normal stress parallel to the local y-coordinate
XY	shear stress
ON	octahedral normal stress
OS	octahedral shear stress
NZE	non-zero elements
BARK	number of non-zero elements in the master stiffness matrix
+RHS	sum of BARK and the non-zero elements (forces) on the right-hand sides of the deflection equations
REDU	non-zero elements remaining in +RHS after reduction to account for support conditions

NOTES:

1. The first page of output is a listing in block tabular form of the input values for the X-coordinates. The coordinates are listed row-by-row, from left to right, in order of the node-point number to which they correspond. Index numbers at the top and to the left of the block assist the user in identifying the node number for each coordinate value. If the node is fully restrained by a support in the X-direction, a letter S appears following the value. The second page gives Y-coordinate data in a similar format. These data are followed by self-explanatory listings of the remaining input data.
2. The calculated output begins with block tabular listings of deflections at each node point. These deflections are relative to the datum coordinate system used to define the input coordinates. Tables of calculated stresses are then presented for each element, row-by-row. The element identification number is shown at the extreme left of each row. The stresses are calculated at the

centroid position for each element.

3. Next, forces in datum coordinates are listed at each node point. These forces are calculated from the computed deflections and thus represent a statement of forces which must be applied at each node to produce the calculated deflections. Generally, a small force will be found, even at nodes which were supposed to be unloaded. The magnitude of the force is an indication of numerical calculation errors. In some cases, oversight errors in the input make themselves apparent in these tables. Additional checking information is provided by a check row which sums the node forces calculated from deflections and also sums the moment of these forces about the origin of the datum coordinates.
4. The last items of output provide information on the initial number of non-zero elements contained in the simultaneous equations which were solved to find the deflections.

EXAMPLE 1

This example shows the preparation of input data and provides a short problem suitable for testing the operation of the program on the user's equipment. Table I shows a listing of the input data for the analysis of the structure and loadings shown in Figure 4.

The running time for this example is 1 minute on the IBM 360 model 40 computer.

TABLE I. LISTING OF INPUT CARDS FOR EXAMPLE 1.

SHORT CHECKOUT CASE FOR MA2B											
1	4	X	12	6	2	4					
5	8	X		• S	• S	• S	• S	• S	• S	• S	
9	12	X		1.1	1.1	1.1	1.1	1.1	1.1	1.1	
1	4	Y		1.	1.	1.	1.	1.	1.	1.	
5	8	Y		1.	1.	1.	1.	1.	1.	1.	
9	12	Y		1.	1.	1.	1.	1.	1.	1.	
9	X			4.	11.						
9	Y			•	•						
10	X			6.	•						
10	Y			•	•						
11	X			6.	•						
11	Y			•	•						
12	X			4.	-11.						
12	Y			•	•						
1	2		1	5	6	3	.50	30000.	.00000065	.3	
2	4		3	7	8	3					
3	6		5	9	10	3					
4	8		7	11	12	3					
5	3		2	6	7	3	.25	30000.	.00000065	.3	
6	7		6	10	11	3					
2											




Figure 4. Structure for Example 1.

EXAMPLE 2

This example tests the ability of MA2B to find the stresses which result from an interference fit between two concentric circular cylinders. One-quarter of the assembly was analyzed using the finite-element pattern shown in Figure 5. This pattern is quite similar to those used for the lug analyses reported in Volume I.

Figure 5 also shows a comparison of the calculated stresses with the exact solution. The stresses from MA2B were in error by less than 2 percent for this case. The complete computer output for this example is shown in Table II. These data show a very symmetrical solution. The data also show that the interference ($i/D = .001$) was introduced by specifying a temperature rise of 134.1°F to the inner cylinder. No mechanical loads were applied.

The running time for this example is 10 minutes on the IBM 360 model 40 computer.

TABLE II. COMPUTER OUTPUT FOR EXAMPLE 2

LUG ANALYSIS NO. 1CO.1									
X COORDINATES AND SURFACES					Y COORDINATES AND SURFACES				
1	0.50C0	C.54eC	0.5550	0.5520	5	C.120	0.6520	0.7720	7
11	0.5020	C.54eC	0.5545	0.5525	6	C.120	0.6515	0.7715	8
21	C.5820	C.62C1	C.7242	C.9311	7	C.120	0.6515	0.7715	9
31	0.6879	C.8910	0.4e45	C.4417	8	C.4555	0.4865	C.5070	10
41	0.353c	C.3861	0.4e23	C.4164	9	C.46C3	0.4679	C.4951	11
51	0.3344	C.3486	0.3597	C.3812	10	C.4228	0.4610	C.5275	12
61	0.2778	C.2966	C.3050	C.35C5	11	C.4538	0.5618	C.5659	13
71	0.2386	C.3030	C.3092	C.3554	12	C.4545	0.6167	C.5871	14
81	0.0	C.0	S	C.C	13	C.0850	0.0826	C.1758	15
				S	14	C.0854	0.0857	C.1851	16
				S	15	C.0856	0.0857	C.2015	17
				S	16	C.0858	0.1208	C.1564	18
				S	17	C.0859	0.1208	C.3393	19
				S	18	C.0859	0.1208	C.5630	20
				S	19	C.0859	0.1208	C.5809	21
				S	20	C.0859	0.1208	C.8090	22
				S	21	C.0859	0.1208	C.32C9	23
				S	22	C.0859	0.1208	C.2688	24
				S	23	C.0859	0.1208	C.2475	25
				S	24	C.0859	0.1208	C.2475	26
				S	25	C.0859	0.1208	C.2475	27
				S	26	C.0859	0.1208	C.2475	28
				S	27	C.0859	0.1208	C.2475	29
				S	28	C.0859	0.1208	C.2475	30
				S	29	C.0859	0.1208	C.2475	31
				S	30	C.0859	0.1208	C.2475	32
				S	31	C.0859	0.1208	C.2475	33
				S	32	C.0859	0.1208	C.2475	34
				S	33	C.0859	0.1208	C.2475	35
				S	34	C.0859	0.1208	C.2475	36
				S	35	C.0859	0.1208	C.2475	37
				S	36	C.0859	0.1208	C.2475	38
				S	37	C.0859	0.1208	C.2475	39
				S	38	C.0859	0.1208	C.2475	40
				S	39	C.0859	0.1208	C.2475	41
				S	40	C.0859	0.1208	C.2475	42
				S	41	C.0859	0.1208	C.2475	43
				S	42	C.0859	0.1208	C.2475	44
				S	43	C.0859	0.1208	C.2475	45
				S	44	C.0859	0.1208	C.2475	46
				S	45	C.0859	0.1208	C.2475	47
				S	46	C.0859	0.1208	C.2475	48
				S	47	C.0859	0.1208	C.2475	49
				S	48	C.0859	0.1208	C.2475	50
				S	49	C.0859	0.1208	C.2475	51
				S	50	C.0859	0.1208	C.2475	52
				S	51	C.0859	0.1208	C.2475	53
				S	52	C.0859	0.1208	C.2475	54
				S	53	C.0859	0.1208	C.2475	55
				S	54	C.0859	0.1208	C.2475	56
				S	55	C.0859	0.1208	C.2475	57
				S	56	C.0859	0.1208	C.2475	58
				S	57	C.0859	0.1208	C.2475	59
				S	58	C.0859	0.1208	C.2475	60
				S	59	C.0859	0.1208	C.2475	61
				S	60	C.0859	0.1208	C.2475	62
				S	61	C.0859	0.1208	C.2475	63
				S	62	C.0859	0.1208	C.2475	64
				S	63	C.0859	0.1208	C.2475	65
				S	64	C.0859	0.1208	C.2475	66
				S	65	C.0859	0.1208	C.2475	67
				S	66	C.0859	0.1208	C.2475	68
				S	67	C.0859	0.1208	C.2475	69
				S	68	C.0859	0.1208	C.2475	70
				S	69	C.0859	0.1208	C.2475	71
				S	70	C.0859	0.1208	C.2475	72
				S	71	C.0859	0.1208	C.2475	73
				S	72	C.0859	0.1208	C.2475	74
				S	73	C.0859	0.1208	C.2475	75
				S	74	C.0859	0.1208	C.2475	76
				S	75	C.0859	0.1208	C.2475	77
				S	76	C.0859	0.1208	C.2475	78
				S	77	C.0859	0.1208	C.2475	79
				S	78	C.0859	0.1208	C.2475	80
				S	79	C.0859	0.1208	C.2475	81
				S	80	C.0859	0.1208	C.2475	82
				S	81	C.0859	0.1208	C.2475	83
				S	82	C.0859	0.1208	C.2475	84
				S	83	C.0859	0.1208	C.2475	85
				S	84	C.0859	0.1208	C.2475	86
				S	85	C.0859	0.1208	C.2475	87
				S	86	C.0859	0.1208	C.2475	88
				S	87	C.0859	0.1208	C.2475	89
				S	88	C.0859	0.1208	C.2475	90
				S	89	C.0859	0.1208	C.2475	91
				S	90	C.0859	0.1208	C.2475	92
				S	91	C.0859	0.1208	C.2475	93
				S	92	C.0859	0.1208	C.2475	94
				S	93	C.0859	0.1208	C.2475	95
				S	94	C.0859	0.1208	C.2475	96
				S	95	C.0859	0.1208	C.2475	97
				S	96	C.0859	0.1208	C.2475	98
				S	97	C.0859	0.1208	C.2475	99
				S	98	C.0859	0.1208	C.2475	100
				S	99	C.0859	0.1208	C.2475	101
				S	100	C.0859	0.1208	C.2475	102
				S	101	C.0859	0.1208	C.2475	103
				S	102	C.0859	0.1208	C.2475	104
				S	103	C.0859	0.1208	C.2475	105
				S	104	C.0859	0.1208	C.2475	106
				S	105	C.0859	0.1208	C.2475	107
				S	106	C.0859	0.1208	C.2475	108
				S	107	C.0859	0.1208	C.2475	109
				S	108	C.0859	0.1208	C.2475	110
				S	109	C.0859	0.1208	C.2475	111
				S	110	C.0859	0.1208	C.2475	112
				S	111	C.0859	0.1208	C.2475	113
				S	112	C.0859	0.1208	C.2475	114
				S	113	C.0859	0.1208	C.2475	115
				S	114	C.0859	0.1208	C.2475	116
				S	115	C.0859	0.1208	C.2475	117
				S	116	C.0859	0.1208	C.2475	118
				S	117	C.0859	0.1208	C.2475	119
				S	118	C.0859	0.1208	C.2475	120
				S	119	C.0859	0.1208	C.2475	121
				S	120	C.0859	0.1208	C.2475	122
				S	121	C.0859	0.1208	C.2475	123
				S	122	C.0859	0.1208	C.2475	124
				S	123	C.0859	0.1208	C.2475	125
				S	124	C.0859	0.1208	C.2475	126
				S	125	C.0859	0.1208	C.2475	127
				S	126	C.0859	0.1208	C.2475	128
				S	127	C.0859	0.1208	C.2475	129
				S	128	C.0859	0.1208	C.2475	130
				S	129	C.0859	0.1208	C.2475	131
				S	130	C.0859	0.1208	C.2475	132
				S	131	C.0859	0.1208	C.2475	133
				S	132	C.0859	0.1208	C.2475	134
				S	133	C.0859	0.1208	C.2475	135
				S	134	C.0859	0.1208	C.2475	136
				S	135	C.0859	0.1208	C.2475	137
				S	136	C.0859	0.1208	C.2475	138
				S	137	C.0859	0.1208	C.2475	139
				S	138	C.0859	0.1208	C.2475	140
				S	139	C.0859	0.1208	C.2475	1

TABLE II - Continued

21	36	28	29	27	3	2900*	C.3220	C.5CCC	C.000000030	0
22	37	25	30	28	3	2900*	C.3220	C.5CCC	C.000000610	0
23	38	30	31	39	3	2900*	C.3220	C.5CCC	C.000000610	0
24	39	31	32	40	3	2900*	C.3220	C.5CCC	C.000000630	0
25	41	32	34	42	3	2900*	C.3220	C.5CCC	C.000000630	134*
26	42	34	35	43	3	2900*	C.3220	C.5CCC	C.000000630	134*
27	44	36	37	45	3	2900*	C.3220	C.5CCC	C.000000630	0
28	45	37	38	46	3	2900*	C.3220	C.5CCC	C.000000630	0
29	46	38	39	47	3	2900*	C.3220	C.5CCC	C.000000630	0
30	47	39	40	48	3	2900*	C.3220	C.5CCC	C.000000630	0
31	49	41	42	46	3	2900*	C.3220	C.5CCC	C.000000630	134*
32	50	42	43	51	3	2900*	C.3220	C.5CCC	C.000000630	134*
33	52	44	45	53	3	2900*	C.3220	C.5CCC	C.000000630	0
34	53	45	46	54	3	2900*	C.3220	C.5CCC	C.000000630	0
35	54	46	47	55	3	2900*	C.3220	C.5CCC	C.000000630	0
36	55	47	48	56	3	2900*	C.3220	C.5CCC	C.000000630	0
37	57	49	50	58	3	2900*	C.3220	C.5CCC	C.000000630	0
38	58	50	51	59	3	2900*	C.3220	C.5CCC	C.000000630	134*
39	60	52	53	61	3	2900*	C.3220	C.5CCC	C.000000630	0
40	61	53	54	62	3	2900*	C.3220	C.5CCC	C.000000630	0
41	62	54	55	63	3	2900*	C.3220	C.5CCC	C.000000630	0
42	63	55	56	64	3	2900*	C.3220	C.5CCC	C.000000630	0
43	65	57	58	66	3	2900*	C.3220	C.5CCC	C.000000630	134*
44	66	58	59	67	3	2900*	C.3220	C.5CCC	C.000000630	134*
45	68	60	61	69	3	2900*	C.3220	C.5CCC	C.000000630	0
46	69	61	62	70	3	2900*	C.3220	C.5CCC	C.000000630	0
47	70	62	63	71	3	2900*	C.3220	C.5CCC	C.000000630	0
48	71	63	64	72	3	2900*	C.3220	C.5CCC	C.000000630	0
49	73	65	66	74	3	2900*	C.3220	C.5CCC	C.000000630	134*
50	74	66	67	75	3	2900*	C.3220	C.5CCC	C.000000630	134*
51	76	68	69	77	3	2900*	C.3220	C.5CCC	C.000000630	0
52	77	69	70	78	3	2900*	C.3220	C.5CCC	C.000000630	0
53	78	70	71	79	3	2900*	C.3220	C.5CCC	C.000000630	0
54	79	71	72	80	3	2900*	C.3220	C.5CCC	C.000000630	0
55	81	73	74	82	3	2900*	C.3220	C.5CCC	C.000000630	134*
56	82	74	75	83	3	2900*	C.3220	C.5CCC	C.000000630	134*
57	84	76	77	85	3	2900*	C.3220	C.5CCC	C.000000630	0
58	85	77	78	86	3	2900*	C.3220	C.5CCC	C.000000630	0
59	96	78	79	87	3	2900*	C.3220	C.5CCC	C.000000630	0
60	87	79	80	88	3	2900*	C.3220	C.5CCC	C.000000630	0
61	11	3	4	12	3	2900*	C.3220	C.5CCC	C.000000630	134*
62	19	11	12	20	1	2900*	C.3220	C.5CCC	C.000000630	134*
63	27	19	20	28	3	2900*	C.3220	C.5CCC	C.000000630	134*
64	35	27	28	36	3	2900*	C.3220	C.5CCC	C.000000630	134*
65	43	35	36	44	3	2900*	C.3220	C.5CCC	C.000000630	134*
66	51	43	44	52	2	2900*	C.3220	C.5CCC	C.000000630	134*
67	54	51	52	60	2	2900*	C.3220	C.5CCC	C.000000630	134*
68	67	59	60	68	3	2900*	C.3220	C.5CCC	C.000000630	134*
69	75	67	68	76	3	2900*	C.3220	C.5CCC	C.000000630	134*
70	93	75	76	84	3	2900*	C.3220	C.5CCC	C.000000630	134*

TABLE II - Continued

LUG ANALYSIS NO. 1C9.1

Y DEFLECTION, CASE 1							
1	2	3	4	5	6	7	8
1 0.415-C5	1. C20F-04	1. 247E-04	1. 466E-04	1. 433E-04	1. 243E-04	1. 115E-C4	5. 365E-05
11 1.232E-05	1. 441F-04	1. 412E-04	1. 357E-C4	1. 228E-04	1. 101E-04	5. 165E-05	1. C08E-04
21 1.2t3t-34	1. 3C6F-C4	1. 142E-04	1. C61E-C4	4. B15F-05	9. 093E-05	1. 111F-04	1. 395E-04
31 1.014E-04	9. 53E-05	4. 374E-C5	1. 253E-C5	1. 009F-04	1. 159E-04	1. 277F-04	1. 224E-04
41 1. H2F-C5	7. 217E-C5	8. d17E-C5	1. C37E-C4	1. C13F-04	9. 714E-05	1. 111F-C4	1. 008E-04
51 7. 329E-C5	8. 419F-C5	8. 421E-05	8. C73E-C5	7. 307E-05	6. 555E-05	7. 885E-C5	9. C21E-05
61 5. 055E-C5	5. 644E-C5	5. 063E-C5	1. 678E-05	3. 154E-05	2. 467E-05	4. 032E-C5	5. 557E-05
71 3. 842F-C5	3. 446E-05	3. 447E-C6	1. 556E-C5	1. 551E-05	2. 294E-05	4. 428E-05	4. 245E-05
81 0. C	C. 9	C. C	0. C	0. C	0. C	1. 945E-C5	1. 744E-05

Y DEFLECTION, CASE 1		Y DEFLECTION, CASE 1		Y DEFLECTION, CASE 1		Y DEFLECTION, CASE 1	
1	2	3	4	5	6	7	8
1 0. C	0. C	0. C	C. C	0. C	0. C	0. C	0. C
11 -1. 051E-05	-2. 294F-05	-2. 243E-05	-2. 149F-C5	-1. 546E-05	-1. 744F-05	-1. 679E-05	-6. 500E-06
21 -4. 079E-C5	-4. 265F-05	-3. 843E-C5	-2. 445E-C5	-2. 68E-05	-4. 635E-05	-5. 662E-05	-2. 853E-C5
31 -5. 643F-C5	-5. C63F-05	-3. 155E-05	-5. 557E-C5	-7. 31CE-05	-8. 620E-05	-8. 424E-05	-6. 509E-05
41 -3. 043F-05	-7. 220E-05	-8. 819E-C5	-1. C37E-C4	-1. 013E-04	-8. 791E-05	-7. 074F-C5	-7. 3C7E-05
51 -1. C09E-04	-1. 181E-04	-1. 160E-04	-1. 112E-C4	-1. 006F-04	-9. 715E-05	-4. 842E-05	-4. 357E-05
61 -1. 277E-04	-1. 224E-04	-1. 1C8E-C4	-5. 937E-C5	-5. 168E-05	-9. 022E-05	-9. 097E-C5	-1. 111E-04
71 -1. 192E-04	-1. 061F-04	-5. 368E-C5	-1. CC8E-C4	-1. 332E-04	-1. 186E-04	-1. 395E-C4	-1. 363E-04
81 -5. 034E-05	-1. 021F-C4	-1. 247E-C4	-1. 467E-C4	-1. 433E-04	-1. 374E-04	-1. 243F-04	-1. 115F-C4

TABLE II - Continued

LUG ANALYSIS NO. 1CC.1

STRESS	XX	YY	XY	ZA	CS	CASE
1	-C.5700	-20.5C75	-0.0016	-7.1592	S.447C	1
2	-2.1230	-14.2874	-0.034C	-7.136E	F.6354	1
3	-2.9095	6.C544	C.000C	1.C483	2.7338	1
4	-2.4911	5.6485	C.0022	1.4526	3.4C54	1
5	-1.4003	4.1575	0.0022	1.4858	2.1461	1
6	-7.4162	3.0875	C.0002	1.1235	1.8914	1
7	-C.3706	-20.5073	C.0011	-7.1553	S.4468	1
8	-2.1219	-19.2868	C.0012	-7.1362	6.4353	1
9	-2.9106	6.C555	-C.0006	1.44E4	2.1249	1
10	-2.4911	5.6450	-C.0002	1.C531	3.4C61	1
11	-1.4000	4.1577	-0.0012	1.CE59	2.7456	1
12	-0.4161	3.7874	-0.0004	1.1238	1.8511	1
13	-0.5697	-20.5066	C.0011	-7.1586	6.4464	1
14	-2.1224	-19.2878	-0.0006	-0.1367	E.6357	1
15	-2.5084	6.C554	-C.0002	1.C49C	2.7335	1
16	-2.4925	5.6504	C.0026	1.0527	3.4C66	1
17	-1.5958	4.1577	-0.0023	1.CE55	2.7458	1
18	-0.4161	3.7875	C.0011	1.1238	1.8512	1
19	-0.3695	-20.5042	C.0011	-0.1553	S.4474	1
20	-2.1223	-19.2882	C.0056	-7.137C	E.6358	1
21	-2.9094	6.C555	-0.0011	1.C488	3.7345	1
22	-2.4908	5.6495	C.0015	1.C529	2.4C68	1
23	-1.6006	4.1569	C.0022	1.CF54	2.7457	1
24	-0.4158	1.7483	-0.0001	1.1242	1.8515	1
25	-0.9704	-20.5083	-0.001C	-7.1556	S.4474	1
26	-2.1221	-19.2865	-0.0115	-7.1362	E.6351	1
27	-2.9110	6.C555	C.0007	1.C415	2.7335	1
28	-2.4915	5.6494	C.0024	1.C526	3.4C68	1
29	-1.6000	4.1569	-C.003C	1.CE64	2.7465	1
30	-0.4162	1.7482	C.0022	1.1254	1.8514	1
31	-0.3698	-20.5075	C.0001	-7.1587	S.4472	1
32	-2.1239	-19.2895	C.002C	-7.1361	E.6367	1
33	-2.9112	6.C555	-0.0002	1.C481	3.7338	1
34	-2.4908	5.6497	-C.0091	1.C733	3.4C58	1
35	-1.6004	4.1576	C.0028	1.C558	2.7660	1
36	-0.4161	3.7882	-C.0002	1.1240	1.8515	1
37	-0.9707	-20.5056	-C.0007	-7.1588	S.4468	1
38	-2.1215	-19.2860	C.002C	-7.1378	E.6362	1
39	-2.9095	6.C543	C.0001	1.C490	3.7343	1
40	-2.4914	5.6491	-C.003C	1.C524	3.4C61	1
41	-1.6003	4.1575	C.0025	1.C524	3.4C57	1
42	-0.4160	3.7882	-C.0022	1.CE58	2.7460	1
43	-0.3695	-20.5065	-C.0002	1.1241	1.8514	1
44	-2.1238	-19.2895	C.002C	-7.1588	S.4472	1
45	-2.9085	6.C56C	-0.0004	1.C490	3.7338	1
46	-2.4923	5.6495	-C.003C	1.C524	3.4C61	1
47	-1.6005	4.1575	C.0025	1.C524	3.4C57	1
48	-0.4162	3.7879	-C.0017	1.C1239	1.8514	1
49	-0.9707	-20.5082	-C.0016	-7.1556	S.4472	1
50	-2.1215	-19.287C	-C.0022	-7.1376	E.6355	1

TABLE II - Continued

LUG ANALYSIS NO. 1C0.1

STRESS	XX	YY	YY	CA	CS	CASE
51	-2.91C7	6.C543	C.0CC3	1.C479	2.7342	1
52	-2.4918	5.6494	0.0071	1.C525	3.4C60	1
53	-1.6001	4.6575	0.0002	1.C658	2.7458	1
54	-C.4164	3.7879	C.00C6	1.1239	1.8914	1
55	-C.97CC	-20.5C85	C.0C13	-7.1595	5.4475	1
56	-2.1230	-19.2884	0.0C41	-7.1371	8.6258	1
57	-2.9098	6.C544	C.0004	1.C482	2.7239	1
58	-2.4911	5.6491	-C.0025	1.C527	3.4C56	1
59	-1.6005	4.8577	-0.0C17	1.C858	2.7461	1
60	-0.4162	3.7882	-0.0CC2	1.1240	1.8915	1
61	-2.7887	-18.6196	-0.0C11	-7.1362	E.1996	1
62	-2.7886	-18.6198	C.0C21	-7.1362	E.1996	1
63	-2.7895	-18.6198	-0.0004	-7.1364	E.1994	1
64	-2.7886	-18.6200	-C.0001	-7.1362	E.1997	1
65	-2.7892	-18.6201	-C.0018	-7.1364	E.1996	1
66	-2.7889	-18.6196	0.0C16	-7.1362	E.1995	1
67	-2.7891	-18.6205	-C.0002	-7.1367	E.2C00	1
68	-2.7897	-18.6201	-C.0001	-7.1366	E.1996	1
69	-2.7889	-18.6203	-C.0019	-7.1364	E.1998	1
70	-2.7888	-18.6206	0.0C1C	-7.1365	E.1999	1

TABLE II - Continued

LUG ANALYSIS INC. 1C0.1									
X FORCE, CASE 1									
1	5.560E-08	-8.152E-07	3	4	5	6	7	8	9
1	-1.192E-06	-1.307E-06	-1.371E-06	-1.364E-07	7.153E-07	3.017E-07	-1.021E-06	-1.042E-07	1C
11	1.553E-06	1.553E-06	1.553E-06	-4.172E-07	1.788E-06	-1.267E-07	2.861E-06	2.984E-07	-9.537E-07
21	2.801E-06	1.553E-06	1.371E-06	1.192E-07	1.907E-06	3.576E-07	-2.980E-07	-9.537E-07	-9.537E-07
31	2.421E-07	-5.960E-07	1.907E-06	3.576E-07	6.557E-07	0.0	2.146E-06	1.527E-06	1.669E-06
41	1.192E-07	1.629E-07	7.749E-07	-2.815E-07	2.325E-06	1.527E-07	8.345E-07	8.345E-07	6.519E-07
51	6.941E-07	-2.146E-06	5.141E-07	1.550E-06	-5.960E-08	1.788E-07	-1.192E-07	-4.176E-07	-1.073E-06
61	4.768E-07	1.0013E-06	1.192E-07	-5.560E-08	-1.192E-07	-5.290E-07	-4.619E-07	-1.192E-06	1.848E-06
71	-2.364E-07	0.0	2.384E-07	-1.192E-07	0.0	-1.192E-06	-4.768E-07	0.0	5.960E-08
81	2.536E-01	3.280E-01	2.178E-01	6.633E-02	-8.861E-02	-2.176E-01	-3.854E-01	-1.844E-01	1.863E-08
Y FORCE, CASE 1									
1	-2.536E-01	-3.216E-01	-2.178E-01	4	5	6	7	8	9
1	7.749E-07	1.888E-07	-4.172E-07	-5.560E-08	0.0	2.176E-01	3.853E-01	1.844E-01	-1.192E-07
11	-1.311E-06	2.080E-06	2.080E-06	1.192E-07	1.192E-07	5.960E-08	-1.192E-07	1.371E-06	-9.537E-07
21	-3.576E-07	-2.344E-07	1.788E-07	1.132E-06	-1.073E-06	-2.384E-07	2.384E-07	5.960E-08	-1.152E-06
31	1.192E-07	1.550E-07	-7.749E-07	-5.537E-07	1.371E-06	-1.907E-06	7.153E-07	-1.192E-06	-5.960E-08
41	1.192E-07	1.550E-07	-7.749E-07	-5.537E-07	1.371E-06	-1.550E-06	-5.960E-08	1.788E-07	-9.537E-07
51	-5.960E-08	0.0	8.537E-08	-2.027E-07	4.172E-07	4.172E-07	-5.960E-08	2.027E-06	-9.537E-07
61	-1.907E-06	-1.322E-06	4.768E-07	-9.537E-07	1.669E-06	-2.146E-06	2.027E-06	-2.861E-06	-6.69E-06
71	-7.153E-07	2.848E-07	-9.537E-07	1.132E-06	-2.623E-06	-1.907E-06	-9.537E-07	-8.345E-07	-1.490E-06
81	1.152E-07	1.0013E-06	-1.490E-06	-1.550E-06	-2.861E-06	-1.609E-06	-3.576E-07	-1.192E-07	5.960E-08
CHECKS, SUM									
NZE	RANK	X-FORCES	Y-FORCES	Z-MOMENTS	CASE				
		-3.946E-05	4.089E-05	-5.177E-06	1				
		1451	1541						
		1541	1397						






Figure 5. Structure and Results for Example 2.



3 2.

B

BLANK PAGE

EXAMPLE 3

This example shows an analysis which is typical of those used to find the K_{br} factors reported in Volume I. The lug considered herein is loaded by a force of 1 kip in a direction 45° to the axis of symmetry of the lug. In the analysis it is assumed that only radial compressive forces exist between the lug and the liner. This corresponds to a perfectly greased liner.

Table III presents the entire output from the computer. The output is made more easily understandable by Figure 6, which shows the finite-element pattern and the numbering system. The node numbers are shown small; the element numbers, large and bold. For clarity, the radial bar elements which connect the pin to the liner, and the liner to the lug, are shown slightly curved; and the radial boundary positions of the liner have been shown with gaps. Two elements, numbers 266 and 267, are not shown. Their purpose is to provide a path for resistance to a tangential force, and thus avoid a singular condition in the master stiffness matrix.

The data in Table III show that a gap was permitted to occur between the liner and the lug by specifying a very low modulus (only 1 ksi) for all radial bar elements that were in tension. The proper assignment of moduli was determined by trial and error.

The tangential stress at the bore of the lug was found by extrapolation of plots of tangential stress along radial lines. Figure 7 shows these plots. Then the tangential stresses at the bore were plotted versus angular position, as shown in Figure 8. The magnitude and location of the maximum stress can be read from Figure 8.

TABLE III. COMPUTER OUTPUT FOR EXAMPLE 3

LUG ANALYSIS NO. 105									
X COORDINATES AND SUPPORTS									
1	2	3	4	5	6	7	8	9	10
C.0	C.0	C.0	C.0	C.0	C.0	0.0	0.0	0.0	0.0
0.1687	0.1429	0.1629	C.1953	C.2386	0.3090	0.2935	0.2939	0.3095	0.3480
0.3480	0.1715	0.4528	0.587F	0.4755	0.4045	0.4417	0.4785	0.4789	0.5113
0.5784	0.6246	0.8050	0.3864	0.4755	0.4755	0.5193	0.5630	0.5820	0.5840
0.601	0.7342	0.9511	0.4938	C.4938	0.5393	0.5847	0.5847	0.6045	0.6440
0.7625	C.9877	C.4CCC	0.5000	C.0000	0.5460	0.5920	0.5920	0.6520	0.6520
0.7720	1.3000	0.4538	0.4938	C.5353	0.5847	0.6345	0.6440	0.7625	0.7625
1.0000	C.3894	0.4755	0.4755	C.5153	0.5630	0.5820	0.6201	C.7342	0.7342
0.9511	1.0000	0.4455	0.4455	0.4865	0.5275	0.5652	0.5809	C.6875	C.6875
0.8910	1.0000	0.3230	0.3230	0.4045	0.4417	0.4789	0.4951	0.5275	0.5275
0.6246	0.3090	1.0CCC0	0.3536	0.3536	0.3416	0.4186	0.4186	0.428	C.4610
0.5629	C.7071	1.0CC00	0.2351	0.2351	0.2939	0.3209	0.3480	0.3480	0.3557
0.4938	0.4832	0.4938	C.72C5	1.0CCC0	0.7347	1.0000	1.0000	1.0000	C.2270
0.2270	C.2479	0.2688	0.2688	0.1778	0.2960	0.3505	0.5675	C.5675	C.5675
0.1246	C.1545	0.1545	0.1545	0.1567	C.1829	0.1829	0.1891	0.2015	0.3050
0.0863	C.3663	S	0.0782	C.0782	C.0854	0.0926	0.0926	0.2386	C.1208
0.1564	C.1935	0.1555	S	0.0	0.0	0.0	0.0	0.0	0.0
0.0	C.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
0.1953	-0.2205	-0.2386	-0.3C9C	-0.3863	-0.3863	-0.2939	-0.2939	-0.3209	-0.3480
-0.1480	-0.3715	-0.4538	-0.5678	-0.5678	-0.7347	-0.7347	-0.7347	-0.4617	-0.4617
201	-0.4789	-0.5113	-0.6244	-0.8050	-1.0000	-1.0000	-1.0000	-0.4755	-0.4755
211	-0.4155	-0.5193	-0.5630	-0.6345	-0.6345	-0.6345	-0.6345	-0.5000	-0.5000
221	-0.5920	-0.5920	-0.6320	-0.7120	-1.0000	-0.4755	-0.4755	-0.5630	-0.5630
231	-0.6011	-0.7142	-0.9511	-0.4045	-0.4417	-0.4789	-0.4789	-0.5113	-0.6246
241	-0.8040	-0.2939	-0.2539	-0.3205	-0.3480	-0.3715	-0.3715	-0.5336	-0.5336
251	-0.1545	-C.1687	-0.1629	-C.1953	-C.1953	-0.2386	-0.2386	-0.5078	-0.5078

TABLE III - Continued

LUG ANALYSIS NO. 105		Y COORDINATES AND SUPPORTS		IC	
	1	2	3	4	5
1	0.5000	0.5000	0.5460	0.5620	0.620
11	0.5173	0.2630	0.5630	0.6011	0.7342
21	0.4785	0.5113	0.6446	0.8690	0.2939
31	0.4203	0.4538	0.5878	0.1236	0.1545
41	0.2015	0.2386	0.3150	0.0712	0.0854
51	0.1208	0.1564	0.40	0.0	0.0
61	0.0	0.0	0.0	0.0	0.0
71	-0.1594	-0.1236	-0.1545	-0.1687	-0.0926
81	-0.3090	-0.4050	-0.4220	-0.2210	-0.1929
91	-0.4540	-0.4540	-0.2351	-0.2476	-0.2688
101	-0.4538	-0.5878	-0.5878	-0.3546	-0.3209
111	-0.5659	-0.7071	-0.7071	-0.7071	-0.3861
121	-0.5275	-0.6246	-0.6246	-0.6246	-0.4186
131	-0.4452	-0.4965	-0.5217	-0.5217	-0.4552
141	-0.3804	-0.4753	-0.4455	-0.5192	-0.5630
151	-1.1888	-1.7500	-1.4938	-0.4938	-0.5363
161	-0.9877	-1.2340	-1.7600	-1.4600	-0.5000
171	-0.6520	-0.7720	-1.1200	-1.2500	-1.7500
181	-0.4911	-0.8800	-0.7242	-0.9111	-1.1488
191	-0.4789	-0.5113	-0.4746	-0.6050	-0.6050
201	-0.3490	-0.3480	-0.3715	-0.4316	-0.5878
211	-0.1565	-0.1687	-0.1625	-0.1625	-0.1953
221	0.0	0.0	0.0	0.0	0.0
231	0.1953	0.2386	0.3050	0.2635	0.2939
241	0.5878	0.4045	0.4417	0.4789	0.4889
251	0.4755	0.5153	0.5630	0.6011	0.7342
LOADS, CASE		1	2	3	4
258 X		0.7C7			
258 Y		0.7C7			

TABLE III - Continued

LUG ANALYSIS NO. 1C:					t	PH	THICK-ARIA	ALPHA	TEM 1	TEM 2	TEM 3	TEM 4	TEM 5
SLEN	P	Q	R	S	YPF	29C00.	C.32C0	C.5CCG	0.000006.	0.			
1	1	9	258	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
2	9	17	258	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
3	17	25	258	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
4	25	25	258	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
5	34	53	258	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
6	53	72	258	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
7	72	93	258	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
8	93	114	258	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
9	114	141	258	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
10	141	164	258	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
11	164	195	34	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
12	195	44	34	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
13	53	53	44	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
14	64	54	53	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
15	54	63	63	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
16	72	53	63	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
17	63	73	72	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
18	73	81	72	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
19	91	72	83	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
20	83	84	93	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
21	94	104	93	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
22	114	93	104	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
23	104	115	114	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
24	115	130	114	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
25	141	114	130	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
26	130	142	141	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
27	142	153	141	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
28	164	141	151	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
29	153	165	164	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
30	10	2	3	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
31	11	3	4	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
32	18	10	11	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
33	19	11	12	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
34	26	18	19	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
35	27	19	20	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
36	16	26	27	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
37	17	27	28	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
38	45	34	37	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
39	40	37	38	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
40	51	45	46	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
41	54	45	47	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
42	64	55	56	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
43	65	56	57	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
44	74	64	65	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
45	75	65	66	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
46	84	74	75	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
47	95	75	86	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
48	95	84	85	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
49	96	85	86	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			
50	105	95	96	C	2	29C00.	C.32C0	C.5CCG	0.000006.	0.			

TABLE III - Continued

LUG ANALYSIS NO. 1CS						PR	THICK-ARFA	ALPHA	TEM 1
ELEM	P	R	S	TYPE	E	C-5C00	C-5C00	0.00000630	0.
51	106	96	57	1C7	3	29C00.	C-3200	0.00000630	0.
52	116	105	96	1C6	3	29C00.	C-3200	0.00000630	0.
53	117	107	105	1C5	3	29C00.	C-3200	0.00000630	0.
54	131	116	117	1C2	3	29C00.	C-3200	0.00000630	0.
55	132	117	118	1C3	3	29C00.	C-3200	0.00000630	0.
56	143	131	132	1C4	3	29C00.	C-3200	0.00000630	0.
57	144	132	133	1C5	3	29C00.	C-3200	0.00000630	0.
58	154	143	144	1C5	3	29C00.	C-3200	0.00000630	0.
59	155	144	145	1C6	3	29C00.	C-3200	0.00000630	0.
60	166	154	155	1C7	3	29C00.	C-3200	0.00000630	0.
61	167	155	156	1C8	3	29C00.	C-3200	0.00000630	0.
62	13	5	6	14	3	29C00.	C-3200	0.00000630	0.
63	14	6	7	15	3	29C00.	C-3200	0.00000630	0.
64	15	7	8	16	3	29C00.	C-3200	0.00000630	0.
65	21	13	14	22	3	29C00.	C-3200	0.00000630	0.
66	22	14	15	23	3	29C00.	C-3200	0.00000630	0.
67	23	15	16	24	3	29C00.	C-3200	0.00000630	0.
68	29	21	22	30	3	29C00.	C-3200	0.00000630	0.
69	30	22	23	31	3	29C00.	C-3200	0.00000630	0.
70	23	32	31	C	2	29C00.	C-3200	0.00000630	0.
71	32	23	24	23	3	29C00.	C-3200	0.00000630	0.
72	39	25	30	40	3	29C00.	C-3200	0.00000630	0.
73	40	30	31	41	3	29C00.	C-3200	0.00000630	0.
74	32	42	41	31	3	29C00.	C-3200	0.00000630	0.
75	42	32	33	43	3	29C00.	C-3200	0.00000630	0.
76	48	39	40	49	3	29C00.	C-3200	0.00000630	0.
77	49	40	41	50	3	29C00.	C-3200	0.00000630	0.
78	50	41	42	51	3	29C00.	C-3200	0.00000630	0.
79	51	42	43	52	3	29C00.	C-3200	0.00000630	0.
80	58	48	49	59	3	29C00.	C-3200	0.00000630	0.
81	55	49	50	60	3	29C00.	C-3200	0.00000630	0.
82	60	50	51	61	3	29C00.	C-3200	0.00000630	0.
83	61	51	52	62	3	29C00.	C-3200	0.00000630	0.
84	67	58	59	68	3	29C00.	C-3200	0.00000630	0.
85	68	59	60	65	3	29C00.	C-3200	0.00000630	0.
86	69	50	61	70	3	29C00.	C-3200	0.00000630	0.
87	70	61	62	71	3	29C00.	C-3200	0.00000630	0.
88	77	67	68	78	3	29C00.	C-3200	0.00000630	0.
89	78	68	69	79	3	29C00.	C-3200	0.00000630	0.
90	79	59	70	8C	3	29C00.	C-3200	0.00000630	0.
91	80	70	71	F1	3	29C00.	C-3200	0.00000630	0.
92	71	82	81	C	2	29C00.	C-3200	0.00000630	0.
93	37	77	76	F9	3	29C00.	C-3200	0.00000630	0.
94	88	78	79	F5	3	29C00.	C-3200	0.00000630	0.
95	49	79	80	80	3	29C00.	C-3200	0.00000630	0.
96	90	80	81	81	3	29C00.	C-3200	0.00000630	0.
97	82	92	91	F1	3	29C00.	C-3200	0.00000630	0.
98	48	87	88	F3	3	29C00.	C-3200	0.00000630	0.
99	99	88	89	1C0	3	29C00.	C-3200	0.00000630	0.
100	100	89	90	1C1	3	29C00.	C-3200	0.00000630	0.

TABLE III - Continued

LOG ANALYSIS NO. 125					E	P	G	R	S	TYPE	PK	THICK-AREA	ALPHA	ITEM 5
SI	EP	P	G	R										
101	101	90	91	102	3	29000.	C.32CC	C.5CC	0.0000630	0.				
102	92	103	107	41	3	29000.	C.32CC	C.5CC	0.0000630	C.				
103	108	98	99	105	3	29000.	C.32CC	C.5CC	0.0000630	0.				
104	109	99	99	100	3	29000.	C.32CC	C.5CC	0.0000630	0.				
105	109	99	100	101	3	29000.	C.32CC	C.5CC	0.0000630	0.				
106	110	100	101	101	3	29000.	C.32CC	C.5CC	0.0000630	0.				
107	102	113	217	162	3	29000.	C.32CC	C.5CC	0.0000630	0.				
108	119	105	109	120	3	29000.	C.32CC	C.5CC	0.0000630	0.				
109	120	109	110	121	3	29000.	C.32CC	C.5CC	0.0000630	0.				
110	121	110	110	112	3	29000.	C.32CC	C.5CC	0.0000630	0.				
111	122	111	112	143	3	29000.	C.32CC	C.5CC	0.0000630	0.				
112	123	112	112	124	C	29000.	C.32CC	C.5CC	0.0000630	0.				
113	126	123	123	124	C	29000.	C.32CC	C.5CC	0.0000630	0.				
114	113	125	125	112	3	29000.	C.32CC	C.5CC	0.0000630	0.				
115	125	127	126	424	3	29000.	C.32CC	C.5CC	0.0000630	0.				
116	129	126	127	128	3	29000.	C.32CC	C.5CC	0.0000630	0.				
117	134	119	120	125	3	29000.	C.32CC	C.5CC	0.0000630	0.				
118	135	120	121	126	3	29000.	C.32CC	C.5CC	0.0000630	0.				
119	135	121	122	127	3	29000.	C.32CC	C.5CC	0.0000630	0.				
120	121	122	123	128	3	29000.	C.32CC	C.5CC	0.0000630	0.				
121	146	123	126	129	3	29000.	C.32CC	C.5CC	0.0000630	0.				
122	139	126	126	129	3	29000.	C.32CC	C.5CC	0.0000630	0.				
123	146	134	135	147	3	29000.	C.32CC	C.5CC	0.0000630	0.				
124	147	145	136	148	3	29000.	C.32CC	C.5CC	0.0000630	0.				
125	149	136	137	149	3	29000.	C.32CC	C.5CC	0.0000630	0.				
126	146	137	138	156	3	29000.	C.32CC	C.5CC	0.0000630	0.				
127	150	128	139	161	3	29000.	C.32CC	C.5CC	0.0000630	0.				
128	152	151	139	140	3	29000.	C.32CC	C.5CC	0.0000630	0.				
129	157	146	147	156	3	29000.	C.32CC	C.5CC	0.0000630	0.				
130	158	147	148	155	3	29000.	C.32CC	C.5CC	0.0000630	0.				
131	156	147	150	160	3	29000.	C.32CC	C.5CC	0.0000630	0.				
132	160	149	150	161	3	29000.	C.32CC	C.5CC	0.0000630	0.				
133	151	150	151	162	3	29000.	C.32CC	C.5CC	0.0000630	0.				
134	151	152	153	152	3	29000.	C.32CC	C.5CC	0.0000630	0.				
135	163	157	154	170	3	29000.	C.32CC	C.5CC	0.0000630	0.				
136	170	154	154	171	3	29000.	C.32CC	C.5CC	0.0000630	0.				
137	171	159	160	172	3	29000.	C.32CC	C.5CC	0.0000630	0.				
138	172	160	161	173	3	29000.	C.32CC	C.5CC	0.0000630	0.				
139	173	161	162	178	3	29000.	C.32CC	C.5CC	0.0000630	0.				
140	174	174	162	161	3	29000.	C.32CC	C.5CC	0.0000630	0.				
141	175	175	174	161	3	29000.	C.32CC	C.5CC	0.0000630	0.				
142	176	176	176	176	3	29000.	C.32CC	C.5CC	0.0000630	0.				
143	177	177	177	177	3	29000.	C.32CC	C.5CC	0.0000630	0.				
144	178	178	178	178	3	29000.	C.32CC	C.5CC	0.0000630	0.				
145	179	179	179	179	3	29000.	C.32CC	C.5CC	0.0000630	0.				
146	180	180	180	180	3	29000.	C.32CC	C.5CC	0.0000630	0.				
147	181	181	181	181	3	29000.	C.32CC	C.5CC	0.0000630	0.				
148	182	182	182	182	3	29000.	C.32CC	C.5CC	0.0000630	0.				
149	183	183	183	183	3	29000.	C.32CC	C.5CC	0.0000630	0.				
150	184	184	184	184	3	29000.	C.32CC	C.5CC	0.0000630	0.				
151	185	185	185	185	3	29000.	C.32CC	C.5CC	0.0000630	0.				
152	186	186	186	186	3	29000.	C.32CC	C.5CC	0.0000630	0.				
153	187	187	187	187	3	29000.	C.32CC	C.5CC	0.0000630	0.				
154	188	188	188	188	3	29000.	C.32CC	C.5CC	0.0000630	0.				
155	189	189	189	189	3	29000.	C.32CC	C.5CC	0.0000630	0.				
156	190	190	190	190	3	29000.	C.32CC	C.5CC	0.0000630	0.				
157	191	191	191	191	3	29000.	C.32CC	C.5CC	0.0000630	0.				
158	192	192	192	192	3	29000.	C.32CC	C.5CC	0.0000630	0.				
159	193	193	193	193	3	29000.	C.32CC	C.5CC	0.0000630	0.				
160	194	194	194	194	3	29000.	C.32CC	C.5CC	0.0000630	0.				
161	195	195	195	195	3	29000.	C.32CC	C.5CC	0.0000630	0.				
162	196	196	196	196	3	29000.	C.32CC	C.5CC	0.0000630	0.				
163	197	197	197	197	3	29000.	C.32CC	C.5CC	0.0000630	0.				
164	198	198	198	198	3	29000.	C.32CC	C.5CC	0.0000630	0.				
165	199	199	199	199	3	29000.	C.32CC	C.5CC	0.0000630	0.				
166	200	200	200	200	3	29000.	C.32CC	C.5CC	0.0000630	0.				
167	201	201	201	201	3	29000.	C.32CC	C.5CC	0.0000630	0.				
168	202	202	202	202	3	29000.	C.32CC	C.5CC	0.0000630	0.				
169	203	203	203	203	3	29000.	C.32CC	C.5CC	0.0000630	0.				
170	204	204	204	204	3	29000.	C.32CC	C.5CC	0.0000630	0.				
171	205	205	205	205	3	29000.	C.32CC	C.5CC	0.0000630	0.				
172	206	206	206	206	3	29000.	C.32CC	C.5CC	0.0000630	0.				
173	207	207	207	207	3	29000.	C.32CC	C.5CC	0.0000630	0.				
174	208	208	208	208	3	29000.	C.32CC	C.5CC	0.0000630	0.				
175	209	209	209	209	3	29000.	C.32CC	C.5CC	0.0000630	0.				
176	210	210	210	210	3	29000.	C.32CC	C.5CC	0.0000630	0.				
177	211	211	211	211	3	29000.	C.32CC	C.5CC	0.0000630	0.				
178	212	212	212	212	3	29000.	C.32CC	C.5CC	0.0000630	0.				
179	213	213	213	213	3	29000.	C.32CC	C.5CC	0.0000630	0.				
180	214	214	214	214	3	29000.	C.32CC	C.5CC	0.0000630	0.				
181	215	215	215	215	3	29000.	C.32CC	C.5CC	0.0000630	0.				
182	216	216	216	216	3	29000.	C.32CC	C.5CC	0.0000630	0.				
183	217	217	217	217	3	29000.	C.32CC	C.5CC	0.0000630	0.				
184	218	218	218	218	3	29000.	C.32CC	C.5CC	0.0000630	0.				
185	219	219	219	219	3	29000.	C.32CC	C.5CC	0.0000630	0.				
186	220	220	220	220	3	29000.	C.32CC	C.5CC	0.0000630	0.				
187	221	221	221	221	3	29000.	C.32CC	C.5CC	0.0000630	0.				
188	222	222	222	222	3	29000.	C.32CC	C.5CC	0.0000630	0.				
189</														

TABLE III - Continued

LUG ANALYSIS NO. 105

ELEM	P	Q	R	S	TYPE	E	F	THICK-ARFA	ALPHA	TEM 1	TEM 2	TEM 3	TEM 4	TEM 5
151	94	96	0	0	1	29000.	C.32CC	C.043C	0.00000630	0.	0.	0.	0.	0.
152	104	106	0	0	1	29000.	C.32CC	C.043C	0.00000630	0.	0.	0.	0.	0.
153	115	117	0	0	1	29000.	C.32CC	C.043C	0.00000630	0.	0.	0.	0.	0.
154	130	132	0	0	1	29000.	C.32CC	C.043C	0.00000630	0.	0.	0.	0.	0.
155	142	144	0	0	1	29000.	C.32CC	C.043C	0.00000630	0.	0.	0.	0.	0.
156	153	155	0	0	1	29000.	C.32CC	C.043C	0.00000630	0.	0.	0.	0.	0.
157	165	167	0	0	1	29000.	C.32CC	C.065C	0.00000630	0.	0.	0.	0.	0.
158	3	5	0	0	1	29000.	C.32CC	C.666C	0.00000630	0.	0.	0.	0.	0.
159	11	13	0	0	1	29000.	C.32CC	C.666C	0.00000630	0.	0.	0.	0.	0.
160	19	21	0	0	1	29000.	C.32CC	C.666C	0.00000630	0.	0.	0.	0.	0.
161	27	29	0	0	1	29000.	C.32CC	C.666C	0.00000630	0.	0.	0.	0.	0.
162	37	35	0	0	1	29000.	C.32CC	C.666C	0.00000630	0.	0.	0.	0.	0.
163	46	48	0	0	1	29000.	C.32CC	C.666C	0.00000630	0.	0.	0.	0.	0.
164	56	58	0	0	1	29000.	C.32CC	C.666C	0.00000630	0.	0.	0.	0.	0.
165	65	67	0	0	1	29000.	C.32CC	C.666C	0.00000630	0.	0.	0.	0.	0.
166	75	77	0	0	1	29000.	C.32CC	C.666C	0.00000630	0.	0.	0.	0.	0.
167	85	87	0	0	1	29000.	C.32CC	C.666C	0.00000630	0.	0.	0.	0.	0.
168	96	98	0	0	1	29000.	C.32CC	C.666C	0.00000630	0.	0.	0.	0.	0.
169	106	108	0	0	1	29000.	C.32CC	C.666C	0.00000630	0.	0.	0.	0.	0.
170	117	119	0	0	1	29000.	C.32CC	C.666C	0.00000630	0.	0.	0.	0.	0.
171	132	134	0	0	1	29000.	C.32CC	C.666C	0.00000630	0.	0.	0.	0.	0.
172	144	146	0	0	1	29000.	C.32CC	C.666C	0.00000630	0.	0.	0.	0.	0.
173	155	157	0	0	1	29000.	C.32CC	C.666C	0.00000630	0.	0.	0.	0.	0.
174	167	169	0	0	1	29000.	C.32CC	C.666C	0.00000630	0.	0.	0.	0.	0.
175	165	176	164	0	2	29000.	C.32CC	C.666C	0.00000630	0.	0.	0.	0.	0.
176	254	164	176	0	2	29000.	C.32CC	C.500C	0.00000630	0.	0.	0.	0.	0.
177	176	187	258	0	2	29000.	C.32CC	C.43C	0.00000630	0.	0.	0.	0.	0.
178	187	158	258	0	2	29000.	C.32CC	C.43C	0.00000630	0.	0.	0.	0.	0.
179	148	210	258	0	2	29000.	C.32CC	C.43C	0.00000630	0.	0.	0.	0.	0.
180	210	218	258	0	2	29000.	C.32CC	C.43C	0.00000630	0.	0.	0.	0.	0.
181	218	226	258	0	2	29000.	C.32CC	C.43C	0.00000630	0.	0.	0.	0.	0.
182	226	234	258	0	2	29000.	C.32CC	C.43C	0.00000630	0.	0.	0.	0.	0.
183	234	242	258	0	2	29000.	C.32CC	C.43C	0.00000630	0.	0.	0.	0.	0.
184	242	250	258	0	2	29000.	C.32CC	C.43C	0.00000630	0.	0.	0.	0.	0.
185	250	1	258	0	2	29000.	C.32CC	C.43C	0.00000630	0.	0.	0.	0.	0.
186	177	167	176	178	3	29000.	C.32CC	C.500C	0.00000630	0.	0.	0.	0.	0.
187	178	167	168	178	3	29000.	C.32CC	C.500C	0.00000630	0.	0.	0.	0.	0.
188	188	177	178	185	3	29000.	C.32CC	C.500C	0.00000630	0.	0.	0.	0.	0.
189	189	178	179	190	3	29000.	C.32CC	C.500C	0.00000630	0.	0.	0.	0.	0.
190	199	188	189	200	3	29000.	C.32CC	C.500C	0.00000630	0.	0.	0.	0.	0.
191	200	189	190	201	3	29000.	C.32CC	C.500C	0.00000630	0.	0.	0.	0.	0.
192	211	159	200	212	3	29000.	C.32CC	C.500C	0.00000630	0.	0.	0.	0.	0.
193	212	200	201	213	3	29000.	C.32CC	C.500C	0.00000630	0.	0.	0.	0.	0.
194	219	211	212	220	3	29000.	C.32CC	C.500C	0.00000630	0.	0.	0.	0.	0.
195	220	212	213	221	3	29000.	C.32CC	C.500C	0.00000630	0.	0.	0.	0.	0.
196	227	219	220	228	3	29000.	C.32CC	C.500C	0.00000630	0.	0.	0.	0.	0.
197	228	220	221	229	3	29000.	C.32CC	C.500C	0.00000630	0.	0.	0.	0.	0.
198	235	227	228	236	3	29000.	C.32CC	C.500C	0.00000630	0.	0.	0.	0.	0.
199	236	228	229	237	3	29000.	C.32CC	C.500C	0.00000630	0.	0.	0.	0.	0.
200	243	235	236	244	3	29000.	C.32CC	C.500C	0.00000630	0.	0.	0.	0.	0.

TABLE III - Continued

LOG ANALYSIS NO. 1C3			ITEM 1			ITEM 2			ITEM 3			ITEM 4			ITEM 5		
LINE	P	C	ITEM 1	ITEM 2	ITEM 3	ITEM 4	ITEM 5	ITEM 6	ITEM 7	ITEM 8	ITEM 9	ITEM 10	ITEM 11	ITEM 12	ITEM 13	ITEM 14	
201	244	145	217	144	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
202	241	243	266	252	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
203	252	244	265	253	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
204	2	251	252	251	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
205	1	252	251	251	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
206	160	169	170	161	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
207	161	170	171	182	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
208	172	163	162	142	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
209	161	172	173	164	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
210	164	173	176	185	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
211	166	165	176	175	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
212	191	160	161	192	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
213	192	161	193	153	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
214	163	153	162	167	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
215	191	161	164	164	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
216	164	184	185	156	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
217	197	196	197	166	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
218	202	151	192	203	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
219	203	152	193	204	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
220	204	193	196	205	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
221	205	154	195	195	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
222	156	156	195	195	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
223	214	202	203	215	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
224	215	203	204	216	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
225	216	204	205	217	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
226	217	205	205	205	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
227	207	206	205	195	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
228	208	207	195	156	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
229	239	204	196	157	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
230	222	214	215	223	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
231	223	215	216	224	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
232	224	216	217	225	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
233	210	222	223	221	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
234	231	223	224	222	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
235	232	224	225	223	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
236	238	230	231	239	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
237	239	231	232	240	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
238	240	232	233	241	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
239	246	238	239	247	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
240	247	239	240	248	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
241	248	240	241	249	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
242	254	246	247	255	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
243	255	247	248	256	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
244	256	248	249	257	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
245	254	254	255	6	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
246	6	255	256	7	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
247	7	256	257	8	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
248	176	178	0	0	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
249	187	185	0	0	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	
250	198	200	0	0	1	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	29000.	

TABLE III - Continued

LUG ANALYSIS NO.	10 ⁵	P	Q	R	S	TYPE	E	PR	THICK-AREA	ALPHA	TEM 1	TEM 2	TEM 3	TEM 4	TEN ⁵
251	210	212	0	0	1	29000.		0.3220	C.0660	0.00000630	0.				
252	218	220	0	0	1	29000.		C.3220	C.0660	0.00000630	0.				
253	226	228	0	0	1	29000.		C.3220	C.0660	0.00000630	0.				
254	234	236	0	0	1	29000.		C.3220	C.0660	0.00000630	0.				
255	242	244	0	0	1	29000.		C.3220	C.0660	0.00000630	0.				
256	250	252	0	0	1	29000.		C.3220	C.0660	0.00000630	0.				
257	178	180	0	0	1	1.		C.3220	C.0660	0.00000630	0.				
258	189	191	0	0	1	1.		C.3220	C.0660	0.00000630	0.				
259	200	202	0	0	1	1.		C.3220	C.0660	0.00000630	0.				
260	212	214	0	0	1	1.		C.3220	C.0660	0.00000630	0.				
261	220	222	0	0	1	1.		C.3220	C.0660	0.00000630	0.				
262	228	230	0	0	1	1.		C.3220	C.0660	0.00000630	0.				
263	236	238	0	0	1	29000.		C.3220	C.0660	0.00000630	0.				
264	244	246	0	0	1	29000.		C.3220	C.0660	0.00000630	0.				
265	252	254	0	0	1	29000.		C.3220	C.0660	0.00000630	0.				
266	25	36	0	0	1	29000.		C.3220	C.0430	0.00000630	0.				
267	28	39	0	0	1	29000.		C.3220	C.0430	0.00000630	0.				

TABLE III - Continued

LUG ANALYSIS NO. 105

X	DEFLECTION	CASE 1	2	3	4	5	6	7	8	9	10
1	5.177E-04	5.502E-04	5.575E-04	5.592E-04	5.642E-04	5.694E-04	5.745E-04	5.801E-04	5.844E-04	5.912E-04	5.940E-04
11	5.477E-04	5.554E-04	5.627E-04	5.695E-04	5.752E-04	5.817E-04	5.875E-04	5.939E-04	5.989E-04	5.147E-04	5.192E-04
21	5.033E-04	5.127E-04	5.233E-04	5.335E-04	5.435E-04	5.535E-04	5.635E-04	5.735E-04	5.835E-04	5.935E-04	5.374E-04
31	5.017E-04	5.074E-04	5.126E-04	5.187E-04	5.247E-04	5.307E-04	5.367E-04	5.427E-04	5.481E-04	5.541E-04	4.911E-04
41	5.573E-04	4.607E-04	4.731E-04	4.861E-04	4.981E-04	5.102E-04	5.166E-04	5.231E-04	5.316E-04	5.398E-04	4.541E-04
51	4.277E-04	4.607E-04	4.731E-04	4.861E-04	4.981E-04	5.102E-04	5.231E-04	5.295E-04	5.320E-04	5.356E-04	4.563E-04
61	3.887E-04	4.148E-04	4.402E-04	4.643E-04	4.881E-04	5.121E-04	5.360E-04	5.607E-04	5.905E-04	6.250E-04	4.625E-04
71	3.825E-04	3.811E-04	3.875E-04	3.935E-04	3.985E-04	3.985E-04	3.985E-04	4.047E-04	4.051E-04	4.067E-04	3.561E-04
81	2.657E-04	2.655E-04	3.490E-04	3.494E-04	3.495E-04	3.495E-04	3.495E-04	3.684E-04	3.684E-04	3.684E-04	3.594E-04
91	2.164E-04	2.177E-04	3.551E-04	3.530E-04	3.520E-04	3.520E-04	3.520E-04	3.546E-04	3.546E-04	3.546E-04	2.997E-04
101	2.144E-04	1.733E-04	1.759E-04	2.244E-04	2.211E-04	2.211E-04	2.211E-04	2.251E-04	2.251E-04	2.251E-04	2.551E-04
111	1.402E-04	1.353E-04	1.445E-04	1.533E-04	1.622E-04	1.622E-04	1.622E-04	1.595E-04	1.595E-04	1.595E-04	2.416E-04
121	1.765E-04	1.547E-04	1.153E-04	1.064E-04	1.105E-04	1.105E-04	1.105E-04	7.679E-05	7.679E-05	7.679E-05	1.575E-04
131	3.101E-04	3.014E-04	2.926E-04	1.641E-04	1.918E-04	1.918E-04	1.918E-04	1.565E-04	1.565E-04	1.565E-04	2.145E-04
141	2.310E-04	3.059E-04	2.958E-04	2.059E-04	2.852E-04	2.852E-04	2.852E-04	1.378E-05	1.378E-05	1.378E-05	0.0
151	5.542E-05	6.0	3.064E-04	2.041E-04	2.628E-04	2.628E-04	2.628E-04	1.470E-04	1.461E-04	1.451E-04	1.271E-04
161	8.609E-05	5.293E-05	0.0	3.316E-04	3.065E-04	3.065E-04	3.065E-04	2.815E-04	1.364E-04	1.364E-04	1.296E-04
171	1.309E-04	1.172E-04	8.394E-05	4.902E-05	C.0	C.0	C.0	3.049E-04	2.932E-04	2.815E-04	1.315E-04
181	1.364E-04	1.260E-04	1.152E-04	E.674E-05	5.376E-05	5.376E-05	5.376E-05	3.156E-04	3.156E-04	3.042E-04	1.315E-04
191	1.669E-04	1.601E-04	1.330E-04	1.066E-04	1.118E-04	1.118E-04	1.118E-04	7.703E-05	0.0	3.376E-04	2.278E-04
201	3.535E-04	2.129E-04	2.059E-04	1.212E-04	1.841E-04	1.841E-04	1.841E-04	1.640E-04	1.640E-04	3.710E-04	3.182E-04
211	4.014E-04	3.579E-04	3.942E-04	2.748E-04	2.707E-04	2.707E-04	2.707E-04	1.660E-04	1.660E-04	3.670E-04	3.625E-04
221	4.370E-04	3.411E-04	3.433E-04	2.471E-04	3.5C5E-04	3.5C5E-04	3.5C5E-04	2.590E-04	2.590E-04	2.388E-04	4.044E-04
231	4.040E-04	4.167E-04	4.333E-04	5.017E-04	5.180E-04	5.180E-04	5.180E-04	4.701E-04	4.701E-04	4.774E-04	4.374E-04
241	4.695E-04	5.249E-04	5.370E-04	5.457E-04	5.542E-04	5.542E-04	5.542E-04	5.250E-04	5.250E-04	4.810E-04	4.555E-04
251	5.495E-04	5.679E-04	4.793E-04	4.822E-04	4.822E-04	4.822E-04	4.822E-04	4.597E-04	4.597E-04	4.724E-04	4.861E-04

TABLE III - Continued

LUG ANALYSIS NO. 105									
Y DEFLECTION, CASE 1									
1	2	3	4	5	6	7	8	9	10
1	1.845E-04	1.815E-04	1.819E-04	1.823E-C4	1.751E-04	1.763E-04	1.684E-04	1.554E-04	1.454E-04
11	1.446E-04	1.441E-04	1.572E-04	1.571E-C4	1.405E-04	1.241E-04	1.270E-04	1.203E-04	1.081E-04
21	1.255E-04	1.194E-04	9.9C4E-C5	8.97E-C5	1.021E-04	9.661E-05	8.735E-05	8.875E-05	7.549E-05
31	6.143E-05	4.585E-05	2.712E-06	1.111E-C4	8.513E-05	8.251E-05	7.081E-05	5.905E-05	4.859E-05
41	3.845E-05	4.423E-06	-5.862E-05	8.013E-C5	8.011E-05	6.728E-05	5.445E-05	4.196E-C5	3.555E-05
51	-1.312E-05	-6.272E-05	1.064E-04	8.010E-C5	8.072E-05	6.748E-05	5.420E-05	3.112E-05	2.306E-05
61	-2.555E-05	-9.539E-05	6.373E-C5	6.468E-C5	7.155E-05	5.878E-05	5.207E-05	1.650E-05	1.160E-05
71	-1.095E-04	1.118E-04	9.078E-05	5.098E-C5	7.916E-05	7.666E-05	1.773E-05	4.032E-05	3.154E-05
81	-9.739E-05	-1.147E-04	1.006E-C4	5.867E-C5	8.938E-05	7.987E-05	1.531E-05	1.184E-C5	5.137E-07
91	-7.674E-05	-1.139E-04	1.252E-04	1.111E-C4	1.071E-04	1.004E-04	9.316E-05	1.038E-05	5.132E-07
101	-1.574E-05	-5.506E-05	-9.674E-05	1.035E-C4	1.202E-04	1.160E-04	1.054E-04	1.054E-04	1.203E-05
111	-4.221E-06	-3.218E-05	1.321E-05	1.444E-C4	1.322E-04	1.281E-04	1.227E-04	1.176E-04	2.251E-05
121	1.554E-05	8.273E-06	-1.310E-05	-2.266E-C5	-8.364E-05	-3.179E-05	-7.062E-05	0.0	0.0
131	1.447E-04	1.347E-04	1.3497E-04	2.288E-C5	2.313E-05	2.246E-05	1.600E-05	7.166E-C7	-1.207E-05
141	1.711E-04	1.624E-04	1.619E-C4	1.582E-C4	1.544E-04	2.096E-05	2.154E-05	2.188E-05	0.0
151	-9.417E-05	0.0	1.612E-C4	1.612E-C4	1.750E-04	1.769E-04	1.849E-05	1.883E-05	8.714E-06
161	1.240E-05	6.143E-C6	0.0	2.030E-C4	2.014E-04	2.014E-04	2.011E-04	2.007E-04	1.953E-05
171	1.656E-05	1.651E-05	1.413E-05	5.819E-C4	0.0	2.390E-04	2.395E-04	2.471E-C4	1.676E-05
181	1.657E-C5	1.364E-05	2.015E-05	2.441E-C5	2.311E-05	0.0	2.707E-04	2.725E-04	1.677E-05
191	7.740E-05	1.076E-05	4.256E-C5	5.780E-C5	8.941E-05	6.678E-05	0.0	2.914E-C4	2.794E-04
201	4.145E-04	4.439E-05	5.769E-05	6.398E-C5	1.166E-04	1.632E-04	1.313E-04	1.051E-C4	3.058E-04
211	1.101E-04	1.201E-04	1.301E-04	7.652E-C5	5.024E-05	1.281E-04	1.969E-04	1.901E-C4	3.066E-04
221	1.327E-04	1.566E-04	1.193E-04	1.557E-C4	2.201E-04	2.882E-04	2.996E-04	2.112E-04	2.220E-04
231	1.447E-04	1.647E-04	2.067E-04	2.659E-C4	2.757E-04	2.853E-04	3.113E-04	3.229E-04	1.344E-04
241	1.452E-04	2.401E-04	2.425E-C4	2.520E-C4	2.588E-04	1.829E-04	1.626E-04	1.653E-04	1.626E-04
251	1.114E-04	2.204E-04	1.855E-04	1.840E-C4	1.801E-04	1.773E-04	1.794E-04	2.176E-04	2.176E-04

TABLE III - Continued

LUG ANALYSIS NO. 1C5		STRESS	XX	YY	XY	XX	YY	XY	CR	CS	CASE
1	-2.3526	-1.0992	0.0622	-1.1503	C.5625	1					
2	-2.4121	-1.1005	0.0344	-1.1715	C.5897	1					
3	-2.5172	-1.1033	0.1555	-1.2668	C.5381	1					
4	-1.21756	-2.5503	0.5103	1.1366	C.5286	1					
5	-2.8936	-1.1092	0.1888	-1.3343	C.5595	1					
6	-2.8195	-0.5675	-0.2027	-1.2925	C.5187	1					
7	-2.3003	-0.7853	-0.5634	-1.0285	C.5227	1					
8	-1.3622	-1.0006	-1.4001	-0.7805	C.5364	1					
9	-0.2843	-1.1577	-1.1672	-0.4940	C.614	1					
10	0.5029	-1.1265	-0.6515	-0.2675	C.645	1					
11	-2.0710	-0.5264	C.1157	-0.5575	C.8227	1					
12	-2.1257	-0.8378	C.2662	-0.5578	C.8555	1					
13	-2.0201	-0.8297	C.2215	-0.9499	C.8486	1					
14	-2.2816	-1.1466	C.2665	-1.1447	C.5550	1					
15	-2.5031	-1.4810	C.2546	-1.3300	C.0487	1					
16	-2.5353	-0.8170	C.1866	-1.1174	C.6776	1					
17	-2.7604	-1.7254	C.2330	-1.4653	C.1544	1					
18	-2.8670	-1.8638	-0.0955	-1.5103	C.1805	1					
19	-2.7279	-0.9228	-0.2054	-1.2116	C.1335	1					
20	-2.4149	-1.8342	-0.2057	-1.4164	C.0433	1					
21	-2.0837	-1.2118	-1.1118	-1.1118	C.5670	1					
22	-1.2855	-0.5815	-0.2412	-0.7553	C.5824	1					
23	-0.5021	-0.5895	-0.5912	-0.5002	C.6556	1					
24	-0.1815	-0.4921	-0.1767	-0.2245	C.2501	1					
25	0.0832	-1.0794	-0.0752	-0.3314	C.5306	1					
26	0.2083	-0.4328	-0.0548	-0.0815	C.2796	1					
27	0.2033	-0.4576	0.0618	-0.0481	C.2617	1					
28	0.1435	-1.2415	0.0616	-0.3665	C.6423	1					
29	0.2938	-0.5427	0.0333	-0.0829	C.3416	1					
30	-0.0476	-0.8476	-0.0152	-0.2892	C.3888	1					
31	0.0091	-0.6354	-0.0022	-0.2088	C.3621	1					
32	-0.0511	-0.6691	-0.0132	-0.2105	C.3104	1					
33	0.0119	-0.8704	-0.0092	-0.3071	C.3589	1					
34	-0.0510	-0.6201	-0.0081	-0.2927	C.2552	1					
35	0.0178	-0.8649	0.0135	-0.0481	C.2641	1					
36	-0.0443	-0.6205	0.0111	-0.2010	C.2974	1					
37	0.0327	-0.8530	-0.0024	-0.2991	C.3521	1					
38	-0.0659	-0.6354	-0.0022	-0.2088	C.3617	1					
39	0.0289	-0.5795	0.0355	-0.3124	C.4108	1					
40	-0.0340	-0.8205	0.0345	-0.1835	C.2814	1					
41	0.0158	-0.6468	0.0276	-0.2855	C.3603	1					
42	-0.0328	-0.7162	0.0233	-0.2103	C.3694	1					
43	0.0327	-0.7425	0.0623	-0.2467	C.3695	1					
44	-0.0213	-0.6111	0.0324	-0.2367	C.3555	1					
45	0.0348	-0.8362	0.0339	-0.2671	C.4631	1					
46	-0.0173	-0.5021	0.0164	-0.1731	C.2609	1					
47	0.0652	-0.9295	0.0655	-0.2648	C.4524	1					
48	-0.0366	-0.4555	-0.0265	-0.1642	C.2880	1					
49	0.0682	-0.9147	-0.0206	-0.3021	C.4167	1					
50	-0.0448	-0.6134	-0.1363	-0.2157	C.3610	1					

TABLE III - Continued

LUG ANALYSIS NO. 105					
STRESS	XX	YY	XY	CX	CY
51	0.0554	-0.8265	-0.1160	-0.2970	C.4143
52	-0.0551	-0.9195	-0.1771	-0.3150	C.4516
53	-0.0038	-0.5465	-0.1533	-0.1834	C.2656
54	-0.0247	-1.0551	0.0391	-0.3595	C.6927
55	-0.0236	-0.4226	0.0364	-0.4487	C.1962
56	-0.0633	-0.9468	0.0143	-0.3367	C.3664
57	0.0279	-0.5215	0.0646	-0.3845	C.2581
58	-0.0444	-0.8693	0.0025	-0.3046	C.3597
59	0.0179	-0.5921	-0.0013	-0.1914	C.2334
60	-0.0383	-0.8669	0.0594	-0.2818	C.3148
61	0.0219	-0.6890	-0.0558	-0.2090	C.3146
62	-1.4903	1.8016	-0.0243	0.1038	1.3661
63	-1.0014	1.7616	-0.0813	0.3201	1.2324
64	-0.2991	2.2579	-0.0464	0.6663	1.1608
65	-1.4046	1.6522	-0.0201	0.0825	1.2494
66	-1.0342	1.8521	-0.0461	0.2860	1.2122
67	-0.2867	2.3496	-0.0042	0.6876	1.1810
68	-1.5274	1.7019	0.0281	0.0582	1.3192
69	-1.0681	1.8875	0.0194	0.2733	1.4223
70	-0.5230	2.0602	0.0131	0.3124	1.1151
71	-0.2955	2.3273	-0.0077	0.6773	1.1730
72	-1.4241	1.8032	0.0612	0.1264	1.2215
73	-1.0936	1.7821	-0.2306	0.2295	1.2001
74	-0.9968	1.5066	0.0368	0.3026	1.2041
75	-0.3116	2.3421	0.0238	0.6768	1.1845
76	-1.3307	1.4991	-0.1407	-0.0106	1.2423
77	-1.3973	1.7791	0.2315	0.1272	1.2136
78	-1.1095	1.4968	0.1511	0.2751	1.2693
79	-0.2913	2.2878	0.0753	0.6655	1.1545
80	-1.8250	2.6491	0.0432	0.0747	1.3829
81	-1.6688	2.0326	0.1605	0.1275	1.3113
82	-1.6947	2.0175	0.2861	0.3076	1.2100
83	-0.3139	2.1935	0.1350	0.6265	1.1205
84	-2.0427	2.5966	0.0931	0.1844	1.5000
85	-1.7976	2.6953	0.2555	0.2326	1.7730
86	-1.2113	2.4012	0.4728	0.4643	1.3300
87	-0.3162	1.5635	0.2256	0.5492	1.0253
88	-2.2808	3.3401	0.0517	0.3531	2.3095
89	-2.0066	3.1134	0.3034	0.3685	2.1210
90	-1.3807	2.5756	0.6125	0.4963	1.7141
91	-0.4462	1.5605	0.4387	0.3716	C.5320
92	0.1846	1.6725	0.1761	0.4190	C.4698
93	-2.4246	4.1835	0.1244	0.5863	2.7313
94	-2.1215	3.8265	0.3421	0.5665	2.4773
95	-1.4476	3.4307	0.6523	0.5170	1.5514
96	-0.6570	1.4308	0.6345	0.2575	1.0141
97	-0.0115	-0.1568	0.3956	-0.0656	C.3395
98	-2.3468	5.0215	C.C885	0.8917	3.0745
99	-1.9970	4.5440	0.3122	0.6490	2.7489
100	-1.1460	3.4955	0.6022	0.7031	2.4812

TABLE III - Continued

LUG ANALYSIS NO. 1C5	X	Y	Z	X	Y	Z	CASE
SINLESS							
1.01	-0.7143	1.5214	C.6061	0.2723	1.0555	1	
1.02	-0.0306	-0.8654	C.4748	-0.2796	C.5655	1	
1.03	-1.7160	5.1937	C.1706	1.3126	C.5244	1	
1.04	-1.3465	5.1947	0.3442	1.2693	2.8156	1	
1.05	-0.9286	3.1746	0.4343	0.5934	2.0285	1	
1.06	-0.5774	1.6713	0.4217	0.3646	1.0138	1	
1.07	0.1275	-1.0271	C.4052	-0.2959	C.6141	1	
1.08	-0.3421	6.5082	0.1604	2.0554	3.1545	1	
1.09	-0.1812	5.4678	0.1459	1.7615	2.6724	1	
1.10	-0.0827	2.8112	0.0256	1.2424	1.8166	1	
1.11	-0.3039	1.8291	-0.6683	0.5034	C.5426	1	
1.12	-0.6685	0.8726	0.1595	0.0600	C.6444	1	
1.13	0.2328	-0.7561	-0.1352	-0.1878	C.4542	1	
1.14	0.3765	-1.2448	0.2456	0.3854	C.6380	1	
1.15	0.1950	-1.4695	C.2223	-0.4540	C.7621	1	
1.16	-0.2719	-2.0572	C.3924	-0.7857	C.5349	1	
1.17	0.2568	6.1914	-0.2946	2.8650	2.1444	1	
1.18	0.3814	5.1565	-0.3746	1.8660	2.3659	1	
1.19	0.3711	3.5552	-0.6115	1.3647	1.6720	1	
1.20	-0.0126	1.7894	-0.6661	0.5910	1.0046	1	
1.21	-0.5665	0.4293	-0.4034	-0.0474	C.5227	1	
1.22	-0.9307	-0.9307	0.5776	-0.3361	C.6331	1	
1.23	0.0965	4.8895	-0.1955	1.6383	2.2659	1	
1.24	0.2812	4.1960	-C.5886	1.4924	1.9746	1	
1.25	0.4169	2.9835	-1.0135	C.733	1.5337	1	
1.26	0.1812	1.5475	-1.2105	0.5763	1.2055	1	
1.27	-0.2352	0.6124	-0.8605	0.1257	C.7885	1	
1.28	-0.0256	-0.2913	C.7511	-0.1056	C.6223	1	
1.29	0.0296	3.2442	-0.2416	1.0914	1.5351	1	
1.30	0.1903	2.8416	-C.6346	1.4922	1.9106	1	
1.31	0.3635	2.1013	-1.3332	C.8236	1.4251	1	
1.32	0.3105	1.1917	-1.5464	0.5007	1.3558	1	
1.33	0.0925	0.5936	-1.2265	0.2254	C.7356	1	
1.34	0.0615	0.1877	C.8970	0.0831	C.7366	1	
1.35	0.2119	1.6600	-0.1662	0.6086	C.7286	1	
1.36	0.2527	1.3232	-0.5891	0.5253	C.7485	1	
1.37	0.2413	1.0318	-1.4613	0.4243	1.2715	1	
1.38	0.4207	0.7775	-1.6690	0.3927	1.3776	1	
1.39	0.4328	0.4405	-1.3825	0.2912	1.1417	1	
1.40	0.1915	0.5195	0.9102	C.8206	C.2369	1	
1.41	-1.6415						
1.42	-1.5324						
1.43	-1.4984						
1.44	-1.5042						
1.45	-1.7200						
1.46	-1.7699						
1.47	-2.0880						
1.48	-2.2428						
1.49	-2.6160						
1.50	-2.5006						

TABLE III - Continued

LUG ANALYSIS NO. 105		XX	YY	XY	CX	CY	CASF
STRESS							
151	-2.2182						1
152	-1.193						1
153	-0.0021						1
154	0.0922						1
155	0.1911						1
156	0.0649						1
157	0.1852						1
158	-1.7628						1
159	-1.6551						1
160	-1.6127						1
161	-1.6192						1
162	-1.8182						1
163	-1.8186						1
164	-2.1175						1
165	-2.4045						1
166	-2.6198						1
167	-2.7207						1
168	-2.4461						1
169	-1.3233						1
170	0.0002						1
171	0.0009						1
172	0.0018						1
173	0.0029						1
174	0.0040						1
175	0.2949			-0.5933	C.0229	-0.0661	C.2521
176	-1.0307			0.7471	C.455	-0.0546	C.2314
177	0.9668			-1.0152	-C.0346	-0.0095	C.8175
178	0.8677			-1.0158	C.0754	-0.016C	C.6125
179	0.8675			-1.018	C.2035	-C.0571	C.76C9
180	C.5961			-1.0551	C.3861	-C.143C	C.1408
181	C.596			-1.036	C.6944	-0.3001	C.7715
182	-0.6245			-1.036C	1.100C	-C.362C	1.CC48
183	-1.4774			-1.0775	C.8652	-C.5548	C.1
184	-2.0292			-1.0905	C.4144	-1.060C	C.8555
185	-2.2855			-1.0555	C.1425	-1.020C	C.5224
186	-0.0438			-0.789C	C.001	-0.2776	C.3629
187	0.0283			-0.6918	-C.0237	-0.2212	C.3335
188	-0.0381			-0.7195	C.0362	-0.2725	C.360C
189	0.0196			-0.701C	C.006	-0.2270	C.362
190	-0.0128			-0.7056	-C.0039	-0.2595	C.344C
191	0.0352			-0.7322	-C.0032	-0.2323	C.3537
192	-0.0352			-0.761C	-C.0121	-0.2657	C.3507
193	0.0254			-0.7165	-C.0056	-0.2305	C.3442
194	-0.0017			-0.3041	-C.055	-C.0816	C.3704
195	0.0227			-0.616C	-C.022C	-C.145	C.3271
196	-0.0582			-0.5035	-C.0662	-C.12C7	C.4166
197	-0.0070			-0.557	-C.059C	-C.1576	C.2787
198	-0.0661			-0.2764	C.1385	-C.2902	C.3548
199	0.0083			-0.5793	C.121C	-C.2170	C.28C0
200	-0.0161			-0.5948	C.0242	-C.2203	C.3609

TABLE III - Continued

LUG ANALYSIS NO. 105		STRESS	XX	YY	XY	LN	LN	CS	CASE
201	0.0640	-0.8193	0.0207	-0.2516	C-4C25				
202	-0.0242	-0.4224	-0.0594	-0.2355	C-3157				
203	-0.0181	-0.7900	-0.0586	-0.2506	C-3895				
204	-0.0199	-0.7906	-0.0314	-0.2769	C-3649				
205	0.0193	-0.7008	-0.0281	-0.2272	C-3358				
206	-0.0072	-1.0586	-0.4015	-0.3715	C-5548				
207	-0.0273	-0.2762	-0.8128	-0.1765	C-6751				
208	0.1197	-0.1916	-1.1727	-0.0174	C-5620				
209	0.0548	0.0394	-1.3115	-0.1476	I-1C03				
210	0.0950	0.1650	-1.0891	0.3870	C-5900				
211	0.3671	1.0071	0.9014	0.4593	C-8454				
212	-0.1534	-2.6440	-1.1674	-0.9398	I-2214				
213	-0.0591	-1.6122	-0.4052	-0.5571	C-8165				
214	0.0559	-0.7593	0.0226	-0.2178	C-3855				
215	0.6118	-0.7443	-0.2728	-0.4538	C-4538				
216	1.3537	0.2814	0.0570	0.5457	C-5848				
217	0.3595	2.0815	0.5960	0.8390	I-0195				
218	-0.1639	-2.3761	-0.1937	-0.1640	C-6460				
219	0.0307	-1.1265	0.5341	-0.4625	I-0625				
220	0.9975	0.2692	0.8816	0.2885	C-76C3				
221	1.3614	1.0000	1.2540	0.7868	I-1738				
222	0.9123	1.4668	-1.2311	0.7430	I-1739				
223	-0.0180	-0.2800	0.4613	-0.1660	C-3566				
224	0.1504	0.3183	1.1765	0.1163	C-5731				
225	0.9316	1.5555	1.4400	0.6958	I-3414				
226	-0.0097	3.4294	C-3441	1.0732	I-6517				
227	-0.0504	3.2026	-0.1203	1.0506	I-5250				
228	-0.0038	1.1203	-C-0449	1.0122	I-4619				
229	0.4812	1.6298	0.4391	1.3367	I-6031				
230	0.0784	2.7692	0.5193	1.3373	I-3573				
231	0.2237	2.1627	1.2420	0.8286	I-1511				
232	0.2796	1.8780	1.1162	0.7172	I-2308				
233	0.4532	5.2603	0.3320	1.6645	I-3520				
234	0.4523	3.9354	0.6236	1.3292	I-6518				
235	0.1693	1.1507	C-3506	0.4467	C-5762				
236	-0.3015	5.5147	-0.3395	1.7377	I-6875				
237	-0.0152	3.6324	-C-4006	1.2124	I-7561				
238	0.0181	1.0495	-0.2284	0.3755	C-9125				
239	-1.0208	4.0540	-0.3026	0.8251	I-4108				
240	-0.0214	3.0593	-C-6045	0.7440	I-7412				
241	-0.1124	1.4506	-0.3663	0.4527	C-7652				
242	-1.0081	2.8019	-0.1105	0.3666	I-5165				
243	-1.0977	2.4510	-0.3743	0.4533	I-4171				
244	-0.2595	1.9290	-0.2374	0.5565	C-5593				
245	-1.0071	2.1628	-0.0710	0.1766	I-9377				
246	-1.0542	2.1514	-0.1844	0.3537	I-3265				
247	-0.2671	2.1810	-0.1102	0.6313	I-1C97				
248	0.0067	0.4984							
249	0.4584								
250	0.1115								

TABLE III - Continued

STRESS	XX	YY	XY	CN	CS	CASE
251	0.1332					1
252	0.1466					1
253	0.0235					1
254	-1.2792					1
255	-1.9588					1
256	-1.8904					1
257	0.0078					1
258	0.0065					1
259	0.0059					1
260	0.0042					1
261	0.0021					1
262	0.0004					1
263	-1.4571					1
264	-2.1193					1
265	-1.9613					1
266	0.0003					1
267	-0.0007					1

TABLE III - Continued

LUG ANALYSIS NO. 105

x	FORCE, CASE 1	2	3	4	5	6	7	8	9	10
1	-1.580E-05	-4.172E-07	-1.329E-05	-1.192E-C7	-4.768E-06	1.192E-06	2.921E-06	-2.444E-06	-1.186E-05	-2.265E-06
11	4.411E-05	8.343E-07	2.568E-06	-1.049E-C5	-2.205E-06	1.013E-06	-1.670E-05	-1.901E-05	-2.265E-06	1.788E-05
21	-4.790E-05	5.252E-07	-5.517E-06	2.051E-C5	-2.313E-05	-3.616E-06	1.893E-05	2.211E-C5	1.312E-05	1.312E-05
31	-7.790E-05	3.161E-05	3.098E-06	-2.567E-C5	-5.022E-06	-7.151E-06	1.527E-05	1.901E-C5	1.017E-05	1.657E-07
41	1.659E-05	7.152E-07	1.948E-06	-1.115E-C5	-1.788E-07	2.116E-05	-1.099E-06	-1.971E-05	2.612E-05	-4.470E-06
51	-1.708E-05	2.771E-07	-7.629E-06	-1.001E-C5	-2.146E-06	1.088E-05	2.322E-06	-3.413E-05	2.541E-C5	-4.552E-06
61	5.007E-06	2.813E-07	-4.157E-06	1.602E-C5	3.577E-06	1.907E-06	-3.965E-06	1.907E-06	2.518E-05	5.066E-06
71	1.073E-06	-5.502E-C5	3.338E-06	-1.476E-05	-1.476E-05	1.907E-06	-1.073E-06	-1.073E-06	-2.30E-06	4.687E-06
81	-8.106E-06	1.132E-06	-1.609E-06	-5.566E-C5	-1.665E-06	-1.665E-06	-1.073E-06	-1.073E-06	-2.30E-06	4.687E-06
91	-6.551E-07	0.0	-6.735E-06	2.552E-C5	4.172E-07	0.0	-9.537E-07	-8.888E-07	-4.891E-07	2.517E-06
101	3.331E-03	-1.212E-06	4.292E-C5	-1.512E-07	-1.927E-06	-1.031E-05	1.967E-06	1.967E-06	1.650E-06	1.650E-06
111	4.016E-06	1.848E-06	1.281E-06	5.902E-C5	2.861E-06	-6.631E-07	1.044E-06	1.311E-06	3.241E-06	3.241E-06
121	8.270E-07	-7.770E-07	-2.053E-06	1.071E-C5	7.600E-07	-2.399E-06	9.545E-07	-1.048E-01	3.751E-03	2.444E-06
131	1.668E-06	-1.550E-06	1.603E-06	-6.759E-C7	1.152E-06	1.635E-06	3.017E-07	2.765E-06	2.100E-06	-3.505E-02
141	-6.616E-06	2.086E-06	-7.749E-07	4.828E-06	-1.778E-06	4.731E-06	1.032E-06	-3.055E-07	1.199E-06	5.327E-07
151	6.922E-C7	-6.134E-02	-2.027E-06	-1.0173E-C6	4.531E-06	4.172E-07	-8.792E-07	7.157E-07	2.272E-C6	3.535E-07
161	-1.768E-07	0.0	-7.500E-02	-1.321E-C6	5.122E-06	-1.235E-06	3.874E-06	2.205E-C6	-1.810E-06	1.371E-06
171	3.017E-06	2.682E-06	3.517E-06	1.110E-C6	-1.185E-01	5.494E-06	0.0	-9.531E-C7	4.705E-06	-1.132E-06
181	1.192E-07	2.361E-07	1.132E-06	7.745E-C7	2.986E-07	-1.166E-01	-2.873E-05	-6.551E-C7	4.768E-06	4.768E-06
191	-1.1550E-05	1.669E-06	4.654E-07	2.861E-C6	1.717E-06	-3.033E-02	-1.711E-C5	5.364E-07	4.715E-C5	4.715E-C5
201	1.431E-05	-1.789E-06	1.669E-06	4.530E-C6	1.311E-06	1.311E-06	3.032E-06	2.741E-06	-1.644E-01	-3.010E-03
211	-1.651E-05	3.25E-05	-2.980E-07	-1.725E-C6	-1.538E-05	5.603E-06	0.0	-1.811E-05	3.052E-05	-1.711E-05
221	1.161E-05	-2.159E-05	6.676E-06	6.676E-06	3.576E-07	-2.366E-05	0.0	4.869E-C5	2.563E-05	-1.812E-05
231	2.593E-05	-2.225E-06	2.384E-06	-2.205E-C5	-2.086E-06	1.609E-05	2.801E-06	-5.304E-C5	1.049E-05	-1.533E-06
241	1.192E-07	-1.866E-05	4.941E-05	-1.091E-C5	7.212E-06	-2.390E-05	-8.047E-06	1.191E-05	1.252E-05	1.150E-05
251	3.815E-06	-1.526E-05	5.531E-C7	C.0	8.523E-06	4.888E-06	2.086E-06	7.071E-01		

TABLE III - Continued

LUG ANALYSIS AC. 105

Y FORCE, CASE 1		2		3		4		5		6		7		8		9		10	
1	1.844E-06	-1.5C7E-06	-1.240E-05	-1.5C7E-06	5.537E-C7	-5.722E-06	1.738E-06	2.623E-06	-3.576E-07	9	9	9	9	9	9	9	9	9	9
11	8.283E-06	1.490E-06	1.907E-06	6.357E-C7	1.431E-06	5.921E-06	-1.651E-05	-1.967E-06	5.954E-06	-2.384E-06	-7.153E-07	-1.651E-06	-1.293E-07	2.861E-06	-1.808E-06	1.402E-06	-1.402E-06	-1.402E-06	-1.402E-06
21	-1.019E-05	-5.264E-C7	-4.459E-C7	7.339E-C7	1.455E-C6	5.960E-07	-1.293E-07	2.384E-07	-5.603E-06	4.043E-07	2.682E-06	-1.663E-06	-1.663E-06	6.557E-07	1.132E-06	3.010E-06	1.152E-06	1.152E-06	1.152E-06
31	-1.118E-08	1.132E-06	-5.560E-07	-1.947E-C6	3.576E-07	6.557E-07	3.695E-07	6.695E-06	-1.132E-06	6.557E-07	2.503E-06	-5.998E-07	-5.998E-07	1.874E-06	2.503E-06	5.998E-07	7.149E-07	7.149E-07	7.149E-07
41	-5.327E-07	-3.576E-C7	0.0	-3.755E-C6	6.557E-07	3.695E-07	6.695E-07	6.695E-06	-1.874E-06	2.503E-06	-5.998E-07	-5.998E-07	-5.998E-07	1.874E-06	2.503E-06	5.998E-07	7.149E-07	7.149E-07	7.149E-07
51	-1.371E-05	-2.384E-06	-5.560E-06	-1.311E-C6	1.132E-06	2.861E-06	-1.874E-06	2.213E-06	-2.213E-06	1.907E-06	-2.811E-06	2.384E-07	-6.557E-07	-6.557E-07	1.777E-06	-2.556E-06	-2.556E-06	-2.556E-06	-2.556E-06
61	-1.490E-06	-3.357E-C7	-2.980E-07	-1.788E-07															
71	2.364E-07	1.455E-C7	-1.6C9E-C6	5.960E-C6	-1.072E-06														
81	2.325E-06	-2.432E-06	-6.537E-07	5.537E-C7	-6.420E-06	6.557E-07	1.192E-06	1.192E-06	-1.192E-06	3.994E-06	-1.013E-06	-2.623E-06	-1.013E-06	-1.013E-06	-2.623E-06	-1.013E-06	-1.013E-06	-1.013E-06	-1.013E-06
91	5.364E-07	-2.027E-06	1.729E-06	1.192E-C7	1.192E-06	1.192E-06	1.192E-06	1.192E-06	-1.192E-06	3.994E-06	-1.013E-06	-2.623E-06	-1.013E-06	-1.013E-06	-2.623E-06	-1.013E-06	-1.013E-06	-1.013E-06	-1.013E-06
101	1.9C7E-06	-4.172E-07	-1.9C9E-06	1.9C7E-C6	1.848E-06	3.517E-06	5.364E-07												
111	-1.788E-07	-5.960E-C6	-1.311E-06	1.073E-C6	2.384E-06	5.960E-07													
121	-1.013E-06	1.6C9E-06	1.152E-07	2.844E-07	2.844E-07	1.52E-06	2.384E-07	3.576E-07	-2.384E-07	1.065E-06	2.584E-07	1.755E-01	6.557E-07	1.755E-01	6.557E-07	1.755E-01	6.557E-07	1.755E-01	6.557E-07
131	-9.537E-07	4.764E-06	2.384E-07	5.364E-07	5.364E-07	-3.576E-07	-2.384E-07	-2.384E-07	1.252E-06	2.584E-07	-5.476E-08	6.233E-02	-2.556E-07						
141	3.695E-06	3.815E-06	-9.537E-07	-2.861E-06	3.338E-06	-2.861E-06													
151	-4.058E-03	1.383E-02	1.788E-07	-5.537E-C7	-9.537E-07	3.397E-06	-3.576E-07	2.384E-07	1.788E-07										
161	4.098E-08	3.725E-C6	-3.0C9E-02	5.537E-C7	2.086E-06	-1.907E-06	-5.122E-06	-5.122E-06	-5.122E-06	2.432E-05	-9.537E-07	8.583E-06	1.907E-06	-2.384E-06	1.907E-06	1.907E-06	1.907E-06	1.907E-06	1.907E-06
171	4.172E-07	1.788E-07	4.172E-07	2.049E-C7	-1.232E-01	-1.232E-01	-1.232E-01	-1.232E-01	-1.232E-01	-2.985E-01	-1.578E-07								
181	1.311E-06	-6.345E-07	4.766E-07	5.560E-C8	-1.578E-07														
191	-2.384E-07	7.153E-C1	5.560E-C6	-4.503E-C6	-5.960E-C7	-5.960E-C7	1.073E-06	1.073E-06	-4.044E-01	-4.044E-01	-1.645E-05								
201	-2.861E-06	-1.252E-06	1.550E-C6	1.013E-C6	-4.172E-07	-4.172E-07	-9.537E-07	-9.537E-07	4.172E-07	4.172E-07	9.537E-07								
211	-1.901E-05	1.717E-05	1.252E-C6	-1.192E-C7	1.311E-06	-1.907E-06	-2.252E-06	-2.252E-06	8.941E-07	9.477E-06	1.907E-06	8.941E-07	1.907E-06	8.941E-07	1.907E-06	8.941E-07	1.907E-06	8.941E-07	1.907E-06
221	1.550E-C6	4.768E-C7	-1.431E-C6	-1.907E-C6	-1.788E-07	-1.788E-07	-6.441E-06	-6.441E-06	-3.815E-06	0.0	0.0	6.537E-07	6.537E-07	0.0	6.537E-07	6.537E-07	0.0	6.537E-07	6.537E-07
231	-2.980E-07	1.907E-06	-1.550E-C6	2.742E-C6	-3.815E-06	-3.815E-06	9.537E-06	9.537E-06	-9.537E-07	1.144E-05	1.144E-05	6.0	1.144E-05	1.144E-05	6.0	1.144E-05	1.144E-05	6.0	1.144E-05
241	-1.010E-06	4.292E-06	-5.722E-C6	1.240E-C5	-3.815E-06	-3.815E-06	1.335E-05	1.335E-05	1.907E-06	2.861E-06	2.861E-06	7.153E-07	7.153E-07	2.861E-06	7.153E-07	2.861E-06	7.153E-07	2.861E-06	7.153E-07
251	-9.537E-C7	7.e29E-06	9.537E-07	-6.583E-C6	-9.537E-07	1.907E-06	1.907E-06	7.071E-01											

CHECKS, SUP	X-FORCES	Y-FORCES	Z-MOMENTS	CASE
NZE	BANK	-2.252D-04	2.893C-04	1
	FRHS	4193		
	REDU	4052		





Figure 6. Structure for Example 3.



le 3.

B






Figure 6 - Continued



B



C






Figure 6 - Continued



B



BLANK PAGE




Figure 7. Tangential Stress Versus Radial Position for Example 3.




Figure 8. Tangential stress versus angular position for Example 3.

SOURCE PROGRAM


PROCESSING INFORMATION

Program MA2B is written in FORTRAN IV (E level) for the IBM system 360. It has been run on a model 40 using the Disc Operating System Version 3, Level (release 17). Four tape drives are required for temporary storage. It can be run without change on any IBM 360 having 128,000 bytes of storage. It may also be run on any computer having a FORTRAN IV compiler with only minor changes, providing sufficient storage is available. The program consists of a main program plus four subroutines.

An approximate running time for an IBM 360 model 40 computer can be found from the following expression:

$$\text{Time} = (\text{number of nodes})^2 / 1000 \text{ minutes}$$

FLOW DIAGRAM FOR MA2B



SOURCE PROGRAM DESCRIPTION

<u>FORTRAN</u>	<u>DESCRIPTION</u>
A	matrix of compatible strain distribution for unit element displacements
AL	direction cosines for PQ direction
AL2	direction cosines for TR direction
BARK	upper part of master stiffness matrix; also DBARK and DBAR
BLK	blank symbol on one of input cards
C	matrix occurring in Hooke's Law
C \int E	an integration over the area of an element, used in development of stiffness matrix
DDSK	element stiffness matrix, datum coordinates
DSK	element stiffness matrix, local coordinates
DQRU	element thermal force matrix, datum coordinates
ECH	matrix used for equilibrium checks
F	matrix which relates assumed arbitrary coefficients in displacement function to the displacements
IBARK	identification number for non-zero element in master stiffness matrix
JLAM	dimension of ALAM array
JLAM2	JLAM/2
MPQRS	an array which contains the scheme for building the master stiffness matrix
NBC	identification of rows in master stiffness matrix corresponding to supports
NCR \int SS	number of supports
NEL	N2 + 1

<u>FORTRAN</u>	<u>Description</u>
NUM	number of elements in upper half of master stiffness matrix
N2	number of nodes X 2
QBAR	array into which the mechanical loads are read at the beginning of the program. The thermal loads are subtracted as they are calculated. When all elements are processed, QBAR = sum of mechanical and thermal loads.
QFRU	element thermal force matrix, local coordinates
SCALEF	scale factor for master stiffness matrix, usually 1.0-5
STRESS	stresses

Notes:

1. Several source program symbols were defined in the list of input symbols.
2. All other source symbols are temporary storage.

FORTRAN LISTING

```

C DIMENSIONED FOR 300 ACDES WITH 6000 NZF
C USE TAPES 10,13,14, 11
C DIMENSION DSK(8,8), ETA(5), IPQRS(4), MCQRS( 8), STRESS(5,5),
C 1 R(12), QDRU( 8,5), TEM(5), ECH(3,5), AL2(2), DDSK(8,8),
C 2 ALAM(8,8), AL(2), RH(2C), WG(9), NBC(300), QBAR(600,5),
C 3 X(300), Y(300), UBAR(600,5), A(3,3), CCE(6), B(3), F(8,8),
C 4 CA(3,8), ATD(8,8), DQCRU(8,5), IBARK(6000), BARK(6000)

C COMMON DBARK, DBAR, X, Y, NBC
C DOUBLE PRECISION ECH,SCALEF,DSK,GCRL,F,CCE,A,DEARK(3000),
C 1 SL43,X31,X41,Y31,Y41,SL41,SC43,H3,H1,T2,T,Y21,OBAR(3000)
C DBAR INTRODUCED BECAUSE ARRAY DBARK(6000) WOULD BE TOO LARGE
C MATCH OUT IF YOU CHANGE COMMON CR EQUIVALENCE STATEMENTS.
C THE ORDER HEREIN ESTABLISHES AN EQUIVALENCE BETWEEN
C DBARK(3001),DBAK(1), AND UBAR(1,1)
C EQUIVALENCE(IPQRS(4),IS),(IPQRS(3),IR),(IPQRS(2),IC),(IPQRS(1),
C EQUIVALENCE(DBARK(1),DBARK(1)),1
C 1 (DBAR(1501), QBAR(1,1))
C SCALEF =1.D-5

10 REWIND 10
13 REWIND 13
14 REWIND 14
15 READ(11,21) RH
16 FORMAT(20A4)
17 FORMAT(1H1 //2X,2CA4/)
18 READ(11,41) BLK, NNODES, NELEM, NC, NLN
19 FORMAT(A1,I9,7I1C)
20 N2= 2*NNODES
21 F7R IBM 360-30 USE N=110, NZE=2100
22 NUM=6000 HERE MUST SET EQUAL TO THE DIMENSION OF IBARK
23 NUM=6000
24 DO 60 L=1,NUM

```

```

60 BARK(L) = 0.          E
C   INITIALIZATION MUST CORRESPOND TO DIMENSIONS OF QBAR
61 DO 62 L=1,600          38
62  BARK(L,J) = 0.          39
63 DO 62 J=1,5          40
64  BARK(L,J) = 0.          41
65 42 EE
66 43 1
67 44 1
68 45 1
69 46 1
70 47 1
71 48 1
72 49 1
73 50 1
74 51 1
75 52 1
76 53 1
77 54 1
78 55 1
79 56 1
80 57 1
81 58 1
82 59 1
83 60 1
84 61 1
85 62 1
86 63 1
87 64 1
88 65 1
89 66 1
90 67 1
91 68 1
92 69 1
93 70 1
94 71 1
95 72 1
96 73 1
97 74 1
98 75 1
99 76 1
100 77 1
101 78 1
102 79 1
103 80 1
104 81 1
105 82 1
106 83 1
107 84 1
108 85 1
109 86 1
110 87 1
111 88 1
112 89 1
113 90 1
114 91 1
115 92 1
116 93 1
117 94 1
118 95 1
119 96 1
120 97 1
121 98 1
122 99 1
123 100 1
124 101 1
125 102 1
126 103 1
127 104 1
128 105 1
129 106 1
130 107 1
131 108 1
132 109 1
133 110 1
134 111 1
135 112 1
136 113 1
137 114 1
138 115 1
139 116 1
140 117 1
141 118 1
142 119 1
143 120 1
144 121 1
145 122 1
146 123 1
147 124 1
148 125 1
149 126 1
150 127 1
151 128 1
152 129 1
153 130 1
154 131 1
155 132 1
156 133 1
157 134 1
158 135 1
159 136 1
160 137 1
161 138 1
162 139 1
163 140 1
164 141 1
165 142 1
166 143 1
167 144 1
168 145 1
169 146 1
170 147 1
171 148 1
172 149 1
173 150 1
174 151 1
175 152 1
176 153 1
177 154 1
178 155 1
179 156 1
180 157 1
181 158 1
182 159 1
183 160 1
184 161 1
185 162 1
186 163 1
187 164 1
188 165 1
189 166 1
190 167 1
191 168 1
192 169 1
193 170 1
194 171 1
195 172 1
196 173 1
197 174 1
198 175 1
199 176 1
200 177 1
201 178 1
202 179 1
203 180 1
204 181 1
205 182 1
206 183 1
207 184 1
208 185 1
209 186 1
210 187 1
211 188 1
212 189 1
213 190 1
214 191 1
215 192 1
216 193 1
217 194 1
218 195 1
219 196 1
220 197 1
221 198 1
222 199 1
223 200 1
224 201 1
225 202 1
226 203 1
227 204 1
228 205 1
229 206 1
230 207 1
231 208 1
232 209 1
233 210 1
234 211 1
235 212 1
236 213 1
237 214 1
238 215 1
239 216 1
240 217 1
241 218 1
242 219 1
243 220 1
244 221 1
245 222 1
246 223 1
247 224 1
248 225 1
249 226 1
250 227 1
251 228 1
252 229 1
253 230 1
254 231 1
255 232 1
256 233 1
257 234 1
258 235 1
259 236 1
260 237 1
261 238 1
262 239 1
263 240 1
264 241 1
265 242 1
266 243 1
267 244 1
268 245 1
269 246 1
270 247 1
271 248 1
272 249 1
273 250 1
274 251 1
275 252 1
276 253 1
277 254 1
278 255 1
279 256 1
280 257 1
281 258 1
282 259 1
283 260 1
284 261 1
285 262 1
286 263 1
287 264 1
288 265 1
289 266 1
290 267 1
291 268 1
292 269 1
293 270 1
294 271 1
295 272 1
296 273 1
297 274 1
298 275 1
299 276 1
300 277 1
301 278 1
302 279 1
303 280 1
304 281 1
305 282 1
306 283 1
307 284 1
308 285 1
309 286 1
310 287 1
311 288 1
312 289 1
313 290 1
314 291 1
315 292 1
316 293 1
317 294 1
318 295 1
319 296 1
320 297 1
321 298 1
322 299 1
323 300 1
324 301 1
325 302 1
326 303 1
327 304 1
328 305 1
329 306 1
330 307 1
331 308 1
332 309 1
333 310 1
334 311 1
335 312 1
336 313 1
337 314 1
338 315 1
339 316 1
340 317 1
341 318 1
342 319 1
343 320 1
344 321 1
345 322 1
346 323 1
347 324 1
348 325 1
349 326 1
350 327 1
351 328 1
352 329 1
353 330 1
354 331 1
355 332 1
356 333 1
357 334 1
358 335 1
359 336 1
360 337 1
361 338 1
362 339 1
363 340 1
364 341 1
365 342 1
366 343 1
367 344 1
368 345 1
369 346 1
370 347 1
371 348 1
372 349 1
373 350 1
374 351 1
375 352 1
376 353 1
377 354 1
378 355 1
379 356 1
380 357 1
381 358 1
382 359 1
383 360 1
384 361 1
385 362 1
386 363 1
387 364 1
388 365 1
389 366 1
390 367 1
391 368 1
392 369 1
393 370 1
394 371 1
395 372 1
396 373 1
397 374 1
398 375 1
399 376 1
400 377 1
401 378 1
402 379 1
403 380 1
404 381 1
405 382 1
406 383 1
407 384 1
408 385 1
409 386 1
410 387 1
411 388 1
412 389 1
413 390 1
414 391 1
415 392 1
416 393 1
417 394 1
418 395 1
419 396 1
420 397 1
421 398 1
422 399 1
423 400 1
424 401 1
425 402 1
426 403 1
427 404 1
428 405 1
429 406 1
430 407 1
431 408 1
432 409 1
433 410 1
434 411 1
435 412 1
436 413 1
437 414 1
438 415 1
439 416 1
440 417 1
441 418 1
442 419 1
443 420 1
444 421 1
445 422 1
446 423 1
447 424 1
448 425 1
449 426 1
450 427 1
451 428 1
452 429 1
453 430 1
454 431 1
455 432 1
456 433 1
457 434 1
458 435 1
459 436 1
460 437 1
461 438 1
462 439 1
463 440 1
464 441 1
465 442 1
466 443 1
467 444 1
468 445 1
469 446 1
470 447 1
471 448 1
472 449 1
473 450 1
474 451 1
475 452 1
476 453 1
477 454 1
478 455 1
479 456 1
480 457 1
481 458 1
482 459 1
483 460 1
484 461 1
485 462 1
486 463 1
487 464 1
488 465 1
489 466 1
490 467 1
491 468 1
492 469 1
493 470 1
494 471 1
495 472 1
496 473 1
497 474 1
498 475 1
499 476 1
500 477 1
501 478 1
502 479 1
503 480 1
504 481 1
505 482 1
506 483 1
507 484 1
508 485 1
509 486 1
510 487 1
511 488 1
512 489 1
513 490 1
514 491 1
515 492 1
516 493 1
517 494 1
518 495 1
519 496 1
520 497 1
521 498 1
522 499 1
523 500 1
524 501 1
525 502 1
526 503 1
527 504 1
528 505 1
529 506 1
530 507 1
531 508 1
532 509 1
533 510 1
534 511 1
535 512 1
536 513 1
537 514 1
538 515 1
539 516 1
540 517 1
541 518 1
542 519 1
543 520 1
544 521 1
545 522 1
546 523 1
547 524 1
548 525 1
549 526 1
550 527 1
551 528 1
552 529 1
553 530 1
554 531 1
555 532 1
556 533 1
557 534 1
558 535 1
559 536 1
560 537 1
561 538 1
562 539 1
563 540 1
564 541 1
565 542 1
566 543 1
567 544 1
568 545 1
569 546 1
570 547 1
571 548 1
572 549 1
573 550 1
574 551 1
575 552 1
576 553 1
577 554 1
578 555 1
579 556 1
580 557 1
581 558 1
582 559 1
583 560 1
584 561 1
585 562 1
586 563 1
587 564 1
588 565 1
589 566 1
590 567 1
591 568 1
592 569 1
593 570 1
594 571 1
595 572 1
596 573 1
597 574 1
598 575 1
599 576 1
600 577 1
601 578 1
602 579 1
603 580 1
604 581 1
605 582 1
606 583 1
607 584 1
608 585 1
609 586 1
610 587 1
611 588 1
612 589 1
613 590 1
614 591 1
615 592 1
616 593 1
617 594 1
618 595 1
619 596 1
620 597 1
621 598 1
622 599 1
623 600 1
624 601 1
625 602 1
626 603 1
627 604 1
628 605 1
629 606 1
630 607 1
631 608 1
632 609 1
633 610 1
634 611 1
635 612 1
636 613 1
637 614 1
638 615 1
639 616 1
640 617 1
641 618 1
642 619 1
643 620 1
644 621 1
645 622 1
646 623 1
647 624 1
648 625 1
649 626 1
650 627 1
651 628 1
652 629 1
653 630 1
654 631 1
655 632 1
656 633 1
657 634 1
658 635 1
659 636 1
660 637 1
661 638 1
662 639 1
663 640 1
664 641 1
665 642 1
666 643 1
667 644 1
668 645 1
669 646 1
670 647 1
671 648 1
672 649 1
673 650 1
674 651 1
675 652 1
676 653 1
677 654 1
678 655 1
679 656 1
680 657 1
681 658 1
682 659 1
683 660 1
684 661 1
685 662 1
686 663 1
687 664 1
688 665 1
689 666 1
690 667 1
691 668 1
692 669 1
693 670 1
694 671 1
695 672 1
696 673 1
697 674 1
698 675 1
699 676 1
700 677 1
701 678 1
702 679 1
703 680 1
704 681 1
705 682 1
706 683 1
707 684 1
708 685 1
709 686 1
710 687 1
711 688 1
712 689 1
713 690 1
714 691 1
715 692 1
716 693 1
717 694 1
718 695 1
719 696 1
720 697 1
721 698 1
722 699 1
723 700 1
724 701 1
725 702 1
726 703 1
727 704 1
728 705 1
729 706 1
730 707 1
731 708 1
732 709 1
733 710 1
734 711 1
735 712 1
736 713 1
737 714 1
738 715 1
739 716 1
740 717 1
741 718 1
742 719 1
743 720 1
744 721 1
745 722 1
746 723 1
747 724 1
748 725 1
749 726 1
750 727 1
751 728 1
752 729 1
753 730 1
754 731 1
755 732 1
756 733 1
757 734 1
758 735 1
759 736 1
760 737 1
761 738 1
762 739 1
763 740 1
764 741 1
765 742 1
766 743 1
767 744 1
768 745 1
769 746 1
770 747 1
771 748 1
772 749 1
773 750 1
774 751 1
775 752 1
776 753 1
777 754 1
778 755 1
779 756 1
780 757 1
781 758 1
782 759 1
783 760 1
784 761 1
785 762 1
786 763 1
787 764 1
788 765 1
789 766 1
790 767 1
791 768 1
792 769 1
793 770 1
794 771 1
795 772 1
796 773 1
797 774 1
798 775 1
799 776 1
800 777 1
801 778 1
802 779 1
803 780 1
804 781 1
805 782 1
806 783 1
807 784 1
808 785 1
809 786 1
810 787 1
811 788 1
812 789 1
813 790 1
814 791 1
815 792 1
816 793 1
817 794 1
818 795 1
819 796 1
820 797 1
821 798 1
822 799 1
823 800 1
824 801 1
825 802 1
826 803 1
827 804 1
828 805 1
829 806 1
830 807 1
831 808 1
832 809 1
833 810 1
834 811 1
835 812 1
836 813 1
837 814 1
838 815 1
839 816 1
840 817 1
841 818 1
842 819 1
843 820 1
844 821 1
845 822 1
846 823 1
847 824 1
848 825 1
849 826 1
850 827 1
851 828 1
852 829 1
853 830 1
854 831 1
855 832 1
856 833 1
857 834 1
858 835 1
859 836 1
860 837 1
861 838 1
862 839 1
863 840 1
864 841 1
865 842 1
866 843 1
867 844 1
868 845 1
869 846 1
870 847 1
871 848 1
872 849 1
873 850 1
874 851 1
875 852 1
876 853 1
877 854 1
878 855 1
879 856 1
880 857 1
881 858 1
882 859 1
883 860 1
884 861 1
885 862 1
886 863 1
887 864 1
888 865 1
889 866 1
890 867 1
891 868 1
892 869 1
893 870 1
894 871 1
895 872 1
896 873 1
897 874 1
898 875 1
899 876 1
900 877 1
901 878 1
902 879 1
903 880 1
904 881 1
905 882 1
906 883 1
907 884 1
908 885 1
909 886 1
910 887 1
911 888 1
912 889 1
913 890 1
914 891 1
915 892 1
916 893 1
917 894 1
918 895 1
919 896 1
920 897 1
921 898 1
922 899 1
923 900 1
924 901 1
925 902 1
926 903 1
927 904 1
928 905 1
929 906 1
930 907 1
931 908 1
932 909 1
933 910 1
934 911 1
935 912 1
936 913 1
937 914 1
938 915 1
939 916 1
940 917 1
941 918 1
942 919 1
943 920 1
944 921 1
945 922 1
946 923 1
947 924 1
948 925 1
949 926 1
950 927 1
951 928 1
952 929 1
953 930 1
954 931 1
955 932 1
956 933 1
957 934 1
958 935 1
959 936 1
960 937 1
961 938 1
962 939 1
963 940 1
964 941 1
965 942 1
966 943 1
967 944 1
968 945 1
969 946 1
970 947 1
971 948 1
972 949 1
973 950 1
974 951 1
975 952 1
976 953 1
977 954 1
978 955 1
979 956 1
980 957 1
981 958 1
982 959 1
983 960 1
984 961 1
985 962 1
986 963 1
987 964 1
988 965 1
989 966 1
990 967 1
991 968 1
992 969 1
993 970 1
994 971 1
995 972 1
996 973 1
997 974 1
998 975 1
999 976 1
1000 977 1
1001 978 1
1002 979 1
1003 980 1
1004 981 1
1005 982 1
1006 983 1
1007 984 1
1008 985 1
1009 986 1
1010 987 1
1011 988 1
1012 989 1
1013 990 1
1014 991 1
1015 992 1
1016 993 1
1017 994 1
1018 995 1
1019 996 1
1020 997 1
1021 998 1
1022 999 1
1023 1000 1
1024 1001 1
1025 1002 1
1026 1003 1
1027 1004 1
1028 1005 1
1029 1006 1
1030 1007 1
1031 1008 1
1032 1009 1
1033 1010 1
1034 1011 1
1035 1012 1
1036 1013 1
1037 1014 1
1038 1015 1
1039 1016 1
1040 1017 1
1041 1018 1
1042 1019 1
1043 1020 1
1044 1021 1
1045 1022 1
1046 1023 1
1047 1024 1
1048 1025 1
1049 1026 1
1050 1027 1
1051 1028 1
1052 1029 1
1053 1030 1
1054 1031 1
1055 1032 1
1056 1033 1
1057 1034 1
1058 1035 1
1059 1036 1
1060 1037 1
1061 1038 1
1062 1039 1
1063 1040 1
1064 1041 1
1065 1042 1
1066 1043 1
1067 1044 1
1068 1045 1
1069 1046 1
1070 1047 1
1071 1048 1
1072 1049 1
1073 1050 1
1074 1051 1
1075 1052 1
1076 1053 1
1077 1054 1
1078 1055 1
1079 1056 1
1080 1057 1
1081 1058 1
1082 1059 1
1083 1060 1
1084 1061 1
1085 1062 1
1086 1063 1
1087 1064 1
1088 1065 1
1089 1066 1
1090 1067 1
1091 1068 1
1092 1069 1
1093 1070 1
1094 1071 1
1095 1072 1
1096 1073 1
1097 1074 1
1098 1075 1
1099 1076 1
1100 1077 1
1101 1078 1
1102 1079 1
1103 1080 1
1104 1081 1
1105 1082 1
1106 1083 1
1107 1084 1
1108 1085 1
1109 1086 1
1110 1087 1
1111 1088 1
1112 1089 1
1113 1090 1
1114 1091 1
1115 1092 1
1116 1093 1
1117 1094 1
1118 1095 1
1119 1096 1
1120 1097 1
1121 1098 1
1122 1099 1
1123 1100 1
1124 1101 1
1125 1102 1
1126 1103 1
1127 1104 1
1128 1105 1
1129 1106 1
1130 1107 1
1131 1108 1
1132 1109 1
1133 1110 1
1134 1111 1
1135 1112 1
1136 1113 1
1137 1114 1
1138 1115 1
1139 1116 1
1140 1117 1
1141 1118 1
1142 1119 1
1143 1110 1
1144 1111 1
1145 1112 1
1146 1113 1
1147 1114 1
1148 1115 1
1149 1116 1
1150 1117 1
1151 1118 1
1152 1119 1
1153 1110 1
1154 1111 1
1155 1112 1
1156 1113 1
1157 1114 1
1158 1115 1
1159 1116 1
1160 1117 1
1161 1118 1
1162 1119 1
1163 1110 1
1164 1111 1
1165 1112 1
1166 1113 1
1167 1114 1
1168 1115 1
1169 1116 1
1170 1117 1
1171 1118 1
1172 1119 1
1173 1110 1
1174 1111 1
1175 1112 1
1176 1113 1
1177 1114 1
1178 1115 1
1179 1116 1
1180 1117 1
1181 1118 1
1182 1119 1
1183 1110 1
1184 1111 1
1185 1112 1
1186 1113 1
1187 1114 1
1188 1115 1
1189 1116 1
1190 1117 1
1191 1118 1
1192 1119 1
1193 1110 1
1194 1111 1
1195 1112 1
1196 1113 1
1197 1114 1
1198 1115 1
1199 1116 1
1200 1117 1
1201 1118 1
1202 1119 1
1203 1110 1
1204 1111 1
1205 1112 1
1206 1113 1
1207 1114 1
1208 1115 1
1209 1116 1
1210 1117 1
1211 1118 1
1212 1119 1
1213 1110 1
1
```

```

78 WRITE(3,91) K, AC, (QBARI2*K ,J), J=1,AC)
C THE NCROSS ROWS AND COLS. TC BE STRUCK FROM K-BAR, AS DICTATED BY
C BOUNDARY CONDITIONS, ARE STORED IN ARRAY NBC(I).
79 IJ = 0
    DD 100 I=1,N2
    IF (BARK(I) - BLK) 90,100,90
90 IJ=IJ + 1
    NBC(IJ) = I
100 CONTINUE
    NCROSS = IJ
    DO 110 I=1,NUM
110 BARK(I) = 0.
    WRITE(13) ((QBARI1,J), I=1,NC)
    SET NZE IBARK DIAGONALS
    NEL=NEL+1
    DO 102 I=1,N2
    BARK(I)=0.
102 IBARK(I)=-1
    IBARK(NEL)=0
    IJ=1
    KNO=1
    DO 740 NN=1,NELEM
    IF ( MOD(NN+49,50) ) 104,103,104
103 WRITE(3,31) RH
    WRITE(3,81) (J,J=1,5)
    81 FORMAT(2X,*ELEM, P, Q, R, S TYPE*,7X,*E*. 8X,*PR*,5X,*THICK-AR100
    1EA*4X,*ALPHA * 515X,*TEM* 121)
    104 READ(1,111) IE,IP,IQ,IR,IS,NTYPE,
    111 FORMAT(6I4,F6.3,2F1C.0,6F5.0)
    IF (WG(1)) 105,118,105
    105 T=WG(1)
    E=WG(2)
    ALPHA=WG(3)
    PR= WG(4)
    DO 108 J=1,NC
    108 TEM(J) = WG(J+4)
    118 DO 120 N=1,NC
    120
    75 E
    76
    77
    78
    79
    80
    81
    82
    83
    84
    85
    86
    87
    88
    89
    90
    91
    92
    93
    94
    95
    96
    97
    98
    99
    100
    101
    102
    103
    104
    105
    106
    107
    108
    109
    110
    21
    E1
    21
    111

```

```

120  ETA(N) = TEP(N) * ALPHA
      XQP=X(IQ)-X(IP)
      YQP=Y(IQ)-Y(IP)
      D1=SQRT(XQP*XQP+YQP*YQP)
      CALCULATE THE PQ DIRECTION COSINES AND AREA*E
      AL(1)=XQP/D1
      AL(2)=YQP/D1
      AE=T*E
      GO TO (130,160,160),NTYPE
      C  BAR CALCULATIONS
      130 JLAM = 4
      DO 150 I=1,2
      ALAM(I,I)=AL(I)
      ALAM(I,I+2)=0.
      ALAM(2,I+2)=AL(I)
      ALAM(2,I)=0.
      DO 140 J=1,NC
      DQORU(I,J)=AL(I)*AE*ETA(J)
      140 DQORU(I+2,J)=-DQORU(I,J)
      DO 150 J=1,2
      DDSK(I,J)=AL(I)*AL(J)*AE/D1
      DDSK(I+2,J)=-DDSK(I,J)
      DDSK(I,J+2)=-DDSK(I,J)
      150 DDSK(I+2,J+2) = DDSK(I,J)
      GO TO 680
      C  TRIANGULAR OR RECTANGULAR PANELS CALCULATIONS.
      160 JLAM=2*(NTYPE+1)
      XRP = X(IR)-X(IP)
      YRP = Y(IR)-Y(IP)
      C  THE TR DIRECTION COSINE CALCULATIONS.
      AL2(1) = AL(2)
      AL2(2) = -AL(1)
      C  CHANGE FROM DATUM TO LOCAL COORDINATES
      Y21= D1
      X31= XRP*AL2(1)+YRP*AL2(2)
      Y31= XRP*AL(1)+YRP*AL(2)
      GO TO (680,176,175),NTYPE
      112   E1
      113   1
      114   1
      115   1
      116   1
      117   1
      118   1
      119   1
      120   1
      121   1
      122   1
      123   21
      124   21
      125   21
      126   21
      127   21
      128   321
      129   321
      130   E21
      131   321
      132   321
      133   321
      134   321
      135   E21
      136   1
      137   1
      138   1
      139   1
      140   1
      141   1
      142   1
      143   1
      144   1
      145   1
      146   1
      147   1
      148   1

```

```

175 X SP= X(I$)-X(IP)
      Y SP= Y(I$)-Y(IP)
      X41= X SP*AL2(1)+ Y SP*AL2(2)
      Y41= X SP*AL(1)+ Y SP*AL(2)
176 DO 180 I=1,8
      DO 180 J=1,8
180 F(L,J)=0.
183 GO TO (680,184,200),NTYPE
184 F(1,1)=Y31/(X31*Y21)-1./X31
      F(1,3)=-Y31/(X31*Y21)
      F(1,5)=1./X31
      F(2,1)=-1./Y21
      F(2,3)=1./Y21
      F(3,1)=1.
      F(4,2)=F(1,1)
      F(4,4)=F(1,3)
      F(4,6)=F(1,5)
      F(5,2)=F(2,1)
      F(5,4)=F(2,3)
      F(6,2)=1.
GO TO 220
200 H1=X31*X41*(Y41-Y31)
      F(1,1)=1.
      F(2,1)=((X31*Y31-X41*Y41)+Y31*Y41*(X41-X31)/Y21)/H1
      F(2,3)=Y31*Y41*(X31-X41)/(H1*Y21)
      F(2,5)=X41*Y41/H1
      F(2,7)=-X31*Y31/H1
      F(3,1)=-1./Y21
      F(3,3)=-F(3,1)
      F(4,1)=((X41-X31)+(X31*Y41-X41*Y31))/Y21/H1
      F(4,3)=(X41*Y31-X31*Y41)/(H1*Y21)
      F(4,5)=-X41/H1
      F(4,7)=X31/H1
      F(5,2)=1.
      F(6,2)=F(2,1)
      F(6,4)=-F(2,3)
      F(6,6)=F(2,5)
185

```

```

F( 6, 8)=F( 2, 7) 186 1
F( 7, 2)=F( 3, 1) 187 1
F( 7, 4)=F( 3, 3) 188 1
F( 8, 2)=F( 4, 1) 189 1
F( 8, 4)=F( 4, 3) 190 1
F( 8, 6)=F( 4, 5) 191 1
F( 8, 8)=F( 4, 7) 192 1
220 DO 230 L=1,3 193 21
DO 230 J=1,3 194 321
DO 230 K=1,8 195 4321
230 A(L,J,K) = 0. 196 EEE1
GO TO (680,235,270),NTYPE
235 DO 240 K=1,JLAM
A(1,1,K) = F(1,K)
A(1,2,K)=F(5,K)
A(1,3,K)=F(2,K)+F(4,K)
240 GO TO 290 201 E1
270 DO 280 K=1,JLAM 202 1
A(1,1,K)=F(2,K)
A(1,2,K)=F(7,K)
A(1,3,K)=F(3,K)+F(6,K)
A(2,2,K)=F(8,K)
A(2,3,K)=F(4,K)
A(3,1,K)=F(4,K)
280 A(3,3,K)=F(8,K) 203 21
290 DO 330 L=1,3 204 21
DO 330 J=1,3 205 21
330 C(L,J)= 0. 206 21
C(1,1)= E/(1.-PR*PR) 207 21
C(2,1)= PR*C(1,1) 208 21
C(3,3)=.5*(1.-PR)*C(1,1) 209 21
C(1,2)= C(2,1) 210 E1
C(2,2)= C(1,1) 211 21
350 CALCULATE COEFFICIENTS FOR A(L,J,K) 212 321
355 DO 355 K=1,6 213 E1
      COE(K)=0. 214 1
GO TO (680,360,370),NTYPE 215 1
221 E1
222 1

```

```

360 COE(1)=.5*T*DABS(X31*Y21)
GO TO 410
370 H1=.5*DABS(X31*Y21)
H2=.5*DABS(X41*Y31-X31*Y41)
COE(1)=T*(H1+H2)
COE(2)=T*(H1*X31/3.+H2*(X31*X41)/3.)
COE(3)=T*(H1*(Y31+Y21)/3.+H2*(Y31+Y41)/3.)
XB=COE(2)/COE(1)
YB=COE(3)/COE(1)
SL32=(Y31-Y21)/X31
SC32=Y21
SL41=Y41/X41
COE(4)=T*(.125*(SL32*SL32*SL41*SL41)*X31**4+SL32*SC32
*X31**3/3.+.25*SC32*SC32*X31*X31)
COE(5)=(.25*(SL32-SL41)*X31**4+SC32*X21**3/3.)*T
COE(6)=((SL32**3-SL41**3)*X31**4/12.+SL32*SL32*SC32*X31**3/3.
1+.5*SL32*SC32*SC32*X31*X31+SC32**3*X31/3.)*T
IF(X31-X41) 385,410,385
385 H4=DABS(X31-X41)
IF(H4-.000000001) 410,410,386
386 SL43=(Y41-Y31)/(X41-X31)
H4=DABS(SL42)
IF(H4-50.) 388,410,410
388 SC43=(X41*Y31-X31*Y41)/(X41-X31)
H1=T*(.125*(SL43*SL43-SL41*SL41)*(X41**4-X31**4)+SL43*SC43*
1.(X41**3-X31**3)/3.+.25*SC43*SC43*(X41*X41-X31*X31))
H2=T*(-.25*(SL43-SL41)*(X41**4-X31**4)+SC43*(X41**3-X31**3)/3.)
H3=T*(SL43**3-SL41**3)*(X41**4-X31**4)/12.+_
1.SL43*SL43*SC43*(X41**3-X31**3)/3.+.5*SL43*SC43*(X41*X41-
2.X31*X31+.5*SC43**3*(X41-X31)/3.)
COE(4)=COE(4)+H1
COE(5)=COE(5)+H2
COE(6)=COE(6)+H3
CALCULATE LOCAL STIFFNESS MATRIX DSK
410 00 420 K=1,8
00 420 J=1,8
420 DSK(J,K)=0.
21 321 322
223 224 225 226 227 228 229 230 231 232 233 234 235 236 237 238 239 240 241 242 243 244 245 246 247 248 249 250 251 252 253 254 255 256 257 258 259

```



```

K=0          297   1
DO 640 J=1,JLAM,2          298   21
DO 640 I=1,2          299   321
K=K+1          300   321
      ALAM (J,K)=AL2(I)          301   321
      ALAM(I,J+1,K)=AL(I)          302   EE1
      CALCULATE Q-BAR = ALAM*Q0^L, STORE IN CCRU(I,J)          303   1
      DU 645 J=1,NC          304   21
      DO 645 I=1,JLAM          305   321
      DQORU(I,J)=0.          306   321
      DO 645 K=1,JLAM          307   4321
      DQORU(I,J)=DQORU(I,J)+ALAM(K,I)*CCRU(K,J)          308   EEE1
      CALCULATE DATUM STIFFNESS MATRIX=DDSK          309   1
      DO 650 K=1,JLAM          310   21
      DO 650 L=1,JLAM          311   321
      DO 650 J=1,JLAM          312   EE1
      ATD(J,K)=0.          313   21
      DO 660 J=1,JLAM          314   321
      DO 660 K=1,JLAM          315   4321
      DO 660 L=1,JLAM          316   EEE1
      ATD(J,K)=ATD(J,K) + ALAP (L,J)*CSK(L,K)
      DO 670 J=1,JLAM          317   21
      DO 670 K=1,JLAM          218   321
      DO 670 L=1,JLAM          319   4321
      DDSK (J,K)=ATD (J,L)*ALAP (L,K) + DDSK (J,K)
      MPQRS CONTAINS THE SCHEME FCR BUILDING TCTAL K MATRIX          320   EEE1
      WRITE(3,681) IE,IP,IQ,IR,IS,NTYPE,E,PR,T,ALPHA,ITEM(J),J=1,NC          321   1
      681 FORMAT(1X,15,4I4,I3,          322   1
      K=0          323   1
      JLAM2=JLAM/2          324   1
      DO 690 I=1,JLAM2          325   1
      DO 690 J=1,2          326   21
      K=K+1          327   321
      690 MPQRS(K)=2*IPQRS(I)-2+J          328   321
      FOR ELEMENT, ADD K-BAR TO TCTAL K-BAR, SUPT. Q-BAR FROM TOTAL P.          329   EE1
      1
      DO 720 LA=1,JLAM          330   1
      KM=MPQRS(LA)          331   21
      DO 700 MN=1,NC          332   21
      333   321

```

```

700  QBAR(KM,MN)=DQORU(LA,MN) + QBAR(KY,MN)
    00 720 L=1, JIAM
    KL=MPQRS(L)
    C
    IF(KM-KL) 702, 702, 720
    IF(KM-KM0) 704, 706, 706
    704  I0=KM
    DEVELOP NZE BARK
    702
    706 00 708 I=I0,NUM
    IF( IBARK(I)+KM) 7C8, 710, 708
    708 CONTINUE
    STOP 708
    710  I0=I
    KM0=KM
    IF(KM-KL) 712, 716, 712
    712  I1=I+1
    DO 714  I=I1,NUM
    IF( IBARK(I)) 717, 717, 713
    713  IF( IBARK(I)-KL) 714, 716, 717
    714 CONTINUE
    STOP 714
    716 BARK(I)=BARK(I)+DOSK(LA,L)
    GO TO 720
    717 DO 718 J=I, NEL
    J1=NEL-J+1
    IBARK(J1+1)=IBARK(J1)
    718 BARK(J1+1)= BARK(J1)
    NEL=NEL+1
    IBARK(I)=KL
    BARK(I)=DDSK(LA,L)
    720 CONTINUE
    WRITE(14) T,AE,AL,ALAN,E,ETA,IE,JLAM,MPQRS,NTYPE,PR,DI,
    1 X31,Y31,
    1 X41,Y41,
    A,B,XB,YB
    740 CONTINUE
    NEL=NEL
    DJ 742 J=1,NC
    742 WRITE(13)(QBAR(I,J),I=1,N2)
    WRITE(10) NEL,(IBARK(I),BARK(I),I =1,NEL)

```

C, Y21, 364 1
365 1
366 E
367
368 1
369 E
370

```

C          ADD QBAR TO BARK
KA=0
DU 756 I=1,N2
DO 756 J=1,NC
  IF(QBAR(I,J)) 754, 755, 754
  754 KA=KA+1
  756 CONTINUE
    NEL=NEL+KA
    I=I+N2+1
    DO 766 I=1,NEL
      J=NEL-I+1
      KB=J+KA
      IBARK(KB)=IBARK(J)
      BARK(KB)=BARK(J)
      IF(IBARK(J)) 758, 758, 766
  758 I=I-1
    DO 762 J1=1,NC
      J2=NC-J1+1
      IF(QBAR(I1,J2)) 760, 762, 760
  760 KA=KA-1
    KB=J+KA
    IBARK(KB)=N2+J2
    BARK(KB)=QBAR(I1,J2)
  762 CONTINUE
  766 CONTINUE
    NEL=NEL1
    NEL2=NEL
C          ELIMINATE VARIABLES AT SUPPORTS
    DO 796 LC=1,NCROSS
      LA=NBC(LC)
      KA=0
      KB=1
      I=0
  776 I=I+1
      IF(IBARK(I)) 778, 794, 788
  778 IF(IBARK(I)+LA) 786, 786, 790
  780 KB=I-KA

```



```

REWIND 14
NP= 50
IF(NC-1) 925,925,924
924 NP=50/(NC+1)
925 VP1=NP-1
DO 1092 NN=1,NELEM
  IF( MOD(NN+NP1,NP) ) 940,930,940
  930 WRITE(3,31) RH
  WRITE (3,951)
951 FORMAT( 2X,*STRESS  XX*9X,*YY*9X,*XY*9X,*CN*9X,*OS*6X,*CASE* / )
940 READ(14) T,AE,AL,ALAM,E,ETA,IE,JLAM,PPCRS,NTYPE,PR,DL, C,
  1 X31,Y31,
  1 X41,Y41,
  A,E,XE,YB
C   SELECT U-BAR-I FROM U-BAR AND STORE IT IN QORU(I,J)
  DO 960 L=1,JLAM
    KI=MPQRS(L)
    DO 960 J=1,NC
      960 QORU(L,J)=UBAR(KI,J)
C   CHANGE COOR. SYSTEMS  ALAM(I,J)= * UBAR
      DO 1000 I=1,JLAM
        DO 990 J=1,NC
          990 R(J)= ALAM(I,KI)*QORU(KI,J)+R(J)
          990 R(J)=0.
        1000 ALAM(I,J)=R(J)
        GO TO 1101,1020,1020,NTYPE
C   BAR STRESSES CALCULATIONS
        1010 DO 1005 I=1,NC
          STRESS(1,I)=(ALAM(2,I)-ALAM(1,I)-ETA(I)*DL)*E/DL
        1005 WRITE (3,1011) IE, STRESS(1,I), I
        1011 FORMAT( 2X, I4, F11.4, 46X, I4 )
        GO TO 1090
C   TRIANGULAR AND RECTANGULAR PLATE STRESSES CALCULATIONS
        1020 DO 1030 J=1,3
          DO 1030 L=1,JLAM
          1030 CA(J,L) = 0.
        DO 1040 J=1,3

```

```

DO 1040 K=1,JLAM 321
DO 1040 L=1,3 482
1040 CA(J,K)=CA(J,K)+ C(L,J)*(A(L,L,K)+A(2,L,K)*XB+A(3,L,K)*YB) 483
DO 1050 K=1,NC 484
DO 1050 J=1,3 485
1050 STRESS(J,K)=0. 486
DO 1060 K=1,NC 487
DO 1060 J=1,3 488
DO 1055 L=1,JLAM 489
1055 STRESS(J,K)= STRESS(J,K)+CA(J,L)*ALAM(L,K) 490
1060 STRESS(J,K)= STRESS(J,K) - B(J)*ETACK; 491
DO 1065 K=1,NC 492
H1=STRESS(1,K) 493
H2=STRESS(2,K) 494
H3=STRESS(3,K) 495
1065 STRESS(5,K) =(H1+H2*H2*(H2-H1)*(H2-H1) + 6.*H3*H3))/3. 496
DO 1072 I=1,NC 497
1072 WRITE (3,1073) IE, (STRESS(K,I), K=1,5), I 498
1073 FORMAT( 2X, 14, 5F11.4, 16) 499
1090 IF(NC-1) 1092,1092,1094 500
1094 WRITE (3,1073) 501
1092 CONTINUE 502
REWIND 10 503
10 READ(10) NEL,(IBARK(I),BARK(I),I=1,NEL) 504
C CALCULATE FORCES 505
CALL SNZMPY (IBARK,BARK,UBAR,QBAR,NC,NUM) 506
REWIND 13 507
13 READ(13)((UBAR(I,J),I=1,N2),J=1,NC) 508
DO 1100 J=1,NC 509
13 READ(13) (BARK(K),K=1,N2) 510
DO 1100 I=1,N2 511
1100 UBAR(I,J)=QBAR(I,J)+UBAR(I,J)-BARK(I) 512
C PRINT FORCES AT NODES 513
CALL PRINT (NC, RH, UBAR, NNODES, 2 ) 514
C MAKE EQUILIBRIUM CHECK 515
DO 1130 J=1,NC 516
517
518 1

```

```

      00 1120 L=1,3
      1120 ECH(L,J)=0.
      DD 1130 K=1,NNODES
      ECH(1,J)=ECH(1,J)+UBAR(2*K-1,J)
      ECH(2,J)=ECH(2,J)+UBAR(2*K,J)
      ECH(3,J)=ECH(3,J)+UBAR(2*K,J)*X(K)-UBAR(2*K-1,J)*Y(K)
      WRITE(3,1121)
      1131 FORMAT(//2X,*CHECKS, SUP9X,*X-FCRCES Y-FCRCES Z-MOMENTS
      1CASE* )
      DU 1140 J=1,NC
      1140 WRITE(3,1141) ( ECH(K,J), K=1,3 ) , J)
      1141 FORMAT(18X,1P3E12.3,17)
      WRITE(3,1142) MEL1,MEL2,MEL3
      1142 FORMAT(2X,0NZE5X,0BARK*110/10X,0RHS*110/10X,0REDU*110)
      1150 READ(1,1151) ICONT
      1151 FORMAT(11)
      GO TO (10,1160),ICON1
      1160 CALL EXIT
      END
      519 21
      520 E1
      521 21
      522 21
      523 21
      524 EE
      525
      526
      527
      528 1
      529 E
      530
      531
      532
      533
      534
      535
      536
      537
      538
      539
      540
      541
      542 1
      543 21
      544 EE
      545 1
      546 21
      547 321
      548 E21
      549 EE
      550 1
      551 21
      552 321
      553 EEE
      SUBROUTINE ATCA (A,C,COE,DSK,JLAM,K1,K2,K3)
      CALCULATES DSK = DSK + CCE(K3)*AT(K1)*C*K2)
      DIMENSION A(3,3,8),C(3,3),CCE(6),DSK(8,8),ATC(8,3)
      DOUBLE PRECISION DSK,COE,A
      DD 210 K=1,3
      DO 210 J=1,JLAM
      210 ATC(J,K) = 0.
      DU 230 J=1,JLAM
      DD 230 K=1,3
      DO 220 L=1,3
      220 ATC(J,K) = ATC(J,K) + A(K1,L,J)*C(L,K)
      230 ATC(J,K) = ATC(J,K) + CCE(K3)
      DU 240 J=1,JLAM
      DD 240 K=1,JLAM
      DO 240 L=1,3
      240 DSK(J,K) = DSK(J,K) + ATC(J,K) + A(K2,L,K)

```

RETURN
END

```

SUBROUTINE GAUSS (I,A,N,MAX,NEL,NRHS,NT,PC)
DIMENSION I(1),A(1)
INTEGER STEP,P,PN,PC
DOUBLE PRECISION A,IRN,PVT
STEP(I)=MOD(I,MAX)+1
PO=1
PN=NEL+1
10 K=PO
P=PN
KN=PN
PVT=A(PO)
NPVT=0
20 K=STEP(K)
NPVT=NPVT+1
IF(I(K)>30,30,20
30 IP=PO
DO 500 L=1,NPVT
I(KN)=I(IP)
A(KN)=A(IP)
A(IP)=A(IP)/PVT
IP=STEP(IP)
500 KN=STEP(KN)
I(KN)=-1
KN=STEP(KN)
J=K-1
IF(K-PO)32,31,35
31 NSTOP=31
GU TO 600
32 IF(J)33,34,36
33 NSTOP=33
GO TO 600
34 J=MAX
35 WRITE(NT) NPVT,((((I)),A(((I))),L=PC),J

```

```

GO TO 37      NPVT, I(L), A(L), L=PO, MX), ((L), A(L), L=1, J)
36 WRITE(INT) 589
37 PO=KN      590
38 NE=NPVT+1  591
39 IF(I(K))40,300,38 592
40 NSTOP=38   593
41 GO TO 600  594
42 P=STEP(P) 595
43 IF(I(P)-N)50,50,150 596
44 IF(I(K)+I(P))51,70,60 597
45 NSTOP=41   598
46 GO TO 600  599
47 IF(I(P)-N)50,50,150 600
48 IF(I(K)+I(P))51,70,60 601
49 NSTOP=51   602
50 GO TO 600  603
51 I(KN)=I(K) 604
52 A(KN)=A(K) 605
53 K=STEP(K)  606
54 KN=STEP(KN) 607
55 NE=NE+1   608
56 IF(I(K))50,200,60 609
57 TRM=A(P)/PYT 610
58 I(KN)=I(K) 611
59 A(KN)=A(K)-TRM*A(P) 612
60 IP=P   613
61 IP=STEP(IP) 614
62 IF(I(IP))85,81,110 615
63 NSTOP=81   616
64 GO TO 600  617
65 K=STEP(K)  618
66 KN=STEP(KN) 619
67 NE=NE+1   620
68 IF(I(K))40,200,100 621
69 I(KN)=I(K) 622
70 A(KN)=A(K) 623
71 GO TO 85   624
72 K=STEP(K)  625

```

```

KN=STEP(KN)
NE=NE+1
IF(I(K))1120,120,130
120 I(KN)=I(IP)
A(KN)=TRM*A(IP)
IP=STEP(IP)
KN=STEP(KN)
NE=NE+1
121 IF(I(K))40,200,40
122 IF(I(K))40,200,40
121 NSTOP=121
GO TO 600
130 IF(I(K)-I(IP))135,14C,145
135 I(KN)=I(K)
A(KN)=A(K)
GO TO 110
140 I(KN)=I(K)
A(KN)=A(K)-TRM*A(IP)
GO TO 75
145 I(KN)=I(IP)
A(KN)=TRM*A(IP)
KN=STEP(KN)
IP=STEP(IP)
NE=NE+1
146 IF(I(IP))100,146,13C
146 NSTOP=146
GO TO 600
150 I(KN)=I(K)
A(KN)=A(K)
K=STEP(K)
KN=STEP(KN)
NE=NE+1
151 IF(I(K))150,20C,150
150 I(KN)=0
NEL=MAX0(NE,NEL)
IF(NEL-MX)210,210,201
201 NSTOP=201
626
627
628
629
630
631
632
633
634
635
636
637
638
639
640
641
642
643
644
645
646
647
648
649
650
651
652
653
654
655
656
657
658
659
660
661
662

```

```

663
664 GO TO 600
665
666
667
668
669
670
671
672
673
674
675
676
677
678
679
680
681
682
683
684
685
686
687
688
689
690
691
692
693
694
695
696
697
698
699

GO TO 600
PN=STEP(KN)
GO TO 10
300 M=M+1
307 DO 400 LL=1,N
      BACKSPACE NT
      READ (NT) NPVT, (I(L), A(LL), L=1, NPVT)
309 BACKSPACE NT
      M=M-NRHS
      IF (M-NPVT) 3C1, 301, 302
301 NSTOP=301
      GO TO 600
302 IM=M
      I(NPVT+1)=0
      K=2
305 IF (I(K)-N) 310, 310, 32C
310 IF (I(K)) 311, 320, 312
311 NSTOP=311
      GO TO 600
312 K=K+1
      GO TO 305
320 KR=1
325 IF (I(K)-N-KR) 340, 330, 34C
330 I(K)=0
      A(IM)=A(K)
      K=K+1
      GO TO 345
340 A(IM)=0
345 KR=KR+1
      IM=IM+1
      IF (IM-N-NRHS) 325, 35C, 350
      IM=M-N-NRHS*(I(K)+I(IM))-1
350 K=2
360 IF (I(K)) 361, 400, 370
361 NSTOP=361
      GO TO 600
370 KM=M+NRHS*(I(K)+I(IM))-1
      IM=M-1

```

```

DO 380 LLL=1,NRHS
  K=N*M+1
  IA=IM+1
  380 A(IM)=A(IM)-A(K)*A(KM)
  <=K+1
  GO TO 360
  400 CONTINUE
  IM=M
  RETURN
  600 WRITE (3,1060) NSTOP
  1060 FORMAT (//T10,•STOP•15)
  CALL EXIT
  END

```

```

700 21
701 21
702 21
703 E1
704 1
705 1
706 E
707
708
709
710
711
712

713
714 1
715 1
716 1
717 E
718 1
719 1
720 1
721 21
722 E1
723 1
724 1
725 21
726 21
727 E1
728 729
730

SUBROUTINE SNZMPY (I,A,B,C,N,M,PX)
DIMENSION A(I),B(600,5),C(600,5),I(11)
DO 10 K=1,N
  DO 10 J=1,M
    10 CIK,J)=0
    DO 100 L=1,MX
    IF (I(L),J(20,150,50)
    20 IA=-I(L)
    25 00 30 J=1,M
    30 CI(A,J)=C(I,A,J)*A(L*B(I,A,J))
    GO TO 100
    50 I=I(L)
    DO 70 J=1,M
    70 CI(A,J)=C(I,A,J)*A(L*B(I,A,J))
    100 CONTINUE
    150 RETURN
    END

```

```

SUBROUTINE PRINT ( NC, NM, UBAR, ANODES, ATY )
DIMENSION RH(20), UBAR(600,5)
731
732

```

```

1
733 21
734 21
735 21
736 21
737 21
738 21
739 21
740 21
741 21
742 21
743 21
744 21
745 21
746 21
747 21
748 21
749 21
750 21
751 21
752 21
753 21
754 21
755 21
756 21
757 21
758 21
759 21
760 21
761 21
762 21
763 21
764 21

00 900 J=1,NC
00 900 K=1,2
WRITE(3,31)RH
31 FORMAT(1H1 // / / 2X,2CA4/ )
GO TO (810,820), K
810 WRITE(3,811)
811 FORMAT( 2X, 'X')
GO TO 822
820 WRITE(3,821)
821 FORMAT( 2X, 'Y')
822 GO TO (825,827),NTY
825 WRITE(3,826) J
826 FORMAT(1H+, ' DEFLECTION, CASE' I2)
GO TO 830
827 WRITE(3,828) J
828 FORMAT(1H+, ' FORCE, CASE' I2)
830 WRITE(3,831) {M,M=1,10}
831 FORMAT( 1X, 5(10X, I2), 1
K2=0
840 K1=K2+1
K2=K1+9
IF(NNODES - K2) 845,846,846
845 K2=NNODES
846 GO TO (850,855), K
850 WRITE(3,851) K1, {UBAR(2*L-1, J), L=K1,K2}
851 FORMAT(1X, I4, 1P$E12.3, 4X, 1P$E12.3)
GO TO 860
855 WRITE(3,851) K1, {UBAR(2*L ,J), L=K1,K2}
860 IF(NNODES-K2) 900,90C,840
900 CONTINUE
910 RETURN
END

```

SHORT CHECKOUT CASE FOR MA2B

12	6	2	4
1	4 X	S	S

Unclassified

Security Classification

DOCUMENT CONTROL DATA - R & D

(Security classification of this body of abstract and indexing annotation must be entered when the overall report is classified)

1. ORIGINATING ACTIVITY (Corporate author) Kaman Aerospace Corporation Old Windsor Road Bloomfield, Connecticut		2a. REPORT SECURITY CLASSIFICATION Unclassified
2b. GROUP		
3. REPORT TITLE FATIGUE STRENGTH OF LUGS CONTAINING LINERS VOLUME II - COMPUTER PROGRAM USED FOR ANALYSES		
4. DESCRIPTIVE NOTES (Type of report and inclusive dates) Final Report		
5. AUTHOR(S) (First name, middle initial, last name) Robert J. Mayerjak		
6. REPORT DATE November 1970	7a. TOTAL NO. OF PAGES 86	7b. NO. OF REFS
8a. CONTRACT OR GRANT NO. DAAJ02-67-C-0066	8b. ORIGINATOR'S REPORT NUMBER(S) USAABLabs Technical Report 70-49B	
8c. PROJECT NO. Task 1F162204A14601	8d. OTHER REPORT NO(S) (Any other numbers that may be assigned this report) KAC Report No. R-850, Volume II	
10. DISTRIBUTION STATEMENT This document is subject to special export controls, and each transmittal to foreign governments or foreign nationals may be made only with prior approval of U. S. Army Aviation Materiel Laboratories, Fort Eustis, Virginia 23604.		
11. SUPPLEMENTARY NOTES Volume II of a 2-volume report	12. SPONSORING MILITARY ACTIVITY U. S. Army Aviation Materiel Laboratories Fort Eustis, Virginia	
13. ABSTRACT This report presents the results of an investigation of the fatigue strength of structural lugs. The program included both experimental and analytical phases which were used in a complementary fashion to formulate design charts for fatigue-loaded steel and titanium lugs containing interference fit liners. These lugs are representative of design practice in highly loaded aircraft applications, particularly that found in helicopter blade attaching systems. A primary element in the analytical study was a two-dimensional structural analysis of lug configurations, which was done by finite-element methods using a computer program, (Volume II). The design charts presented will permit the designer to rapidly select lug proportions in either steel or titanium that will satisfy structural requirements for a range of steady and vibratory loading. The designs are considered to be particularly applicable to helicopter rotor and control systems.		

DD FORM 1 NOV 1973
1473
REPLACES DD FORM 1473, 1 JAN 64, WHICH IS
OBsolete FOR ARMY USE.

Unclassified

Security Classification

Unclassified

Security Classification

14. KEY WORDS	LINK A		LINK B		LINK C	
	ROLE	WT	ROLE	WT	ROLE	WT
Fatigue Strength of Steel and Titanium Structural Lugs						
Two-dimensional Structural Analysis						
Aircraft Design						
Finite-Element Computer Program						

Unclassified

Security Classification

9710-70